# UNCLASSIFIED

AD

431737

## DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION, ALEXANDRIA, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.



# 431737

CATALOGED BY DDC
AS AD No.

RADIANT EMISSION FROM HIGH TEMPERATURE EQUILIBRIUM AIR

DASA 1435 RM 63TMP-44

GENERAL ELECTRIC COMPANY SANTA BARBARA CALIFORNIA

GAR + 61664

usla B

## RADIANT EMISSION FROM HIGH TEMPERATURE EQUILIBRIUM AIR

Douglas H. Archer

DASA 1435 18 October 1963

Prepared for: Defense Atomic Support Agency

Washington 25, D.C.

under Contract DA 49-146-XZ-038

Prepared by: TEMPO

General Electric Company Santa Barbara, California

as RM 63TMP-44

#### **ACKNOWLEDGMENT**

The writer gratefully acknowledges the assistance of Mr. T. A. Hoffman who programmed the equations leading to the tables herein presented.

#### ABSTRACT

The spectral distribution of the energy radiated by equilibrium air in the temperature range from  $3000^{\circ}$  to  $9000^{\circ}$ K has been computed for density ratios of  $10^{-4}$ ,  $10^{-5}$  and  $10^{-6}$ . The results are an extension of the work of Breene and Nardone to the lower density ratios, and cover the wave number range from 1250 to 56,000 cm<sup>-1</sup>.

#### RM 63TMP-44

#### TABLE OF CONTENTS

-	Page
ABSTRACT	ii
INTRODUCTION	1
METHOD OF EXTENSION	1
USE OF THE TABLES	3
REFERENÇES	4

### RADIANT EMISSION FROM HIGH TEMPERATURE EQUILIBRIUM AIR

#### INTRODUCTION

The spectral distribution of the energy radiated by equilibrium air in the temperature range from  $3000^{\circ}$  to  $9000^{\circ}$ K and in the density ratio  $(\rho/\rho_{0})$  range from  $10^{2}$  to  $10^{-3}$  has been computed by Breene and Nardone<sup>1</sup>. For some purposes (such as determination of the photo-detachment rate by the radiant emission from hot air at high altitudes), however, it is necessary to know the spectral emission for density ratios smaller than  $10^{-3}$ . This can be obtained, as is indicated in the next section, from the work of Breene and Nardone, together with the work of Gilmore<sup>2</sup> on the equilibrium composition of hot air.

Calculations have been performed to obtain the radiant emission for the temperature range indicated above, and for density ratios of  $10^{-4}$ ,  $10^{-5}$  and  $10^{-6}$ . The results are presented in tabular form in this report and cover the wave number range from 1250 to 56,000 cm<sup>-1</sup>.

#### METHOD OF EXTENSION

Let  $Q_i(\nu, \, \rho/\rho_o \,, \, T)$  be the power radiated per centimeter<sup>3</sup> per steradian per micron at a frequency  $\nu$  by the  $i^{th}$  spectral component of air at temperature T and density ratio  $\rho/\rho_o$ . For low air densities, this power is proportional to the number,  $n_i$ , of particles which radiate the  $i^{th}$  spectral component. But  $n_i$  can be expressed as  $i^{th}$ 

$$n_{i} = 5.3498 \times 10^{19} \left(\frac{\rho}{\rho_{o}}\right) \Psi_{i} \left(\frac{\rho}{\rho_{o}}, T\right)$$
 (1)

where  $\Psi_{i}$  ( $\rho/\rho_{0}$ , T), the number of i<sup>th</sup> type particles per air atom, is given in Reference 2. Consequently the power radiated by the i<sup>th</sup> spectral component when the density ratio is  $10^{-n}$ , may be written in terms of that for a density ratio of  $10^{-3}$  (for a given temperature) as

$$Q_{i} (v, \frac{\rho}{\rho_{o}} = 10^{-n}, T) = g_{i}(n, T) Q_{i}(v, \frac{\rho}{\rho_{o}} = 10^{-3}, T)$$
 (2)

where

$$g_{i}(n, T) = 10^{-n+3} \frac{\Psi_{i}(\frac{\rho}{\rho} = 10^{-n}, T)}{\Psi_{i}(\frac{\rho}{\rho} = 10^{-3}, T)}$$
 (3)

The total radiated power, at frequency  $\,\nu\,$ , due to all spectral components is simply

$$Q(v, \frac{\rho}{\rho_0} = 10^{-n}, T) = \sum_i g_i(n, T) Q_i(v, \frac{\rho}{\rho_0} = 10^{-3}, T)$$
 (4)

The spectral components which were included in the computations of Reference 1 are the following:

- 1... The beta system of NO
- 2. The gamma system of NO
- 3. The Schuman-Runge system of O2
- 4. The first positive system of N<sub>2</sub>
- 5. The second positive system of N,
- 6. The first negative system of  $N_2^{\dagger}$
- 7. The infrared spectrum of NO

- 8. The bound free continuum of O
- 9. The free free continuum of O
- 10. The free free continuum of N.

The values of  $Q_i(v, \rho/\rho_0 = 10^{-3})$ , T), for each of the above spectral components, were obtained from Reference 1, and the values of  $g_i(n, T)$  were computed from the results given in Reference 2. The total radiant emission, expressed in watts per cm<sup>3</sup> per steradian per micron, was then computed from Equation 4.

The spectral emissivity per cm (expressed in terms of wave numbers,  $\stackrel{\sim}{\nu}$  ), defined in Reference 1 as

$$\varepsilon \left( \widetilde{\vee}, \frac{\rho}{\rho_{o}}, T \right) = 1 - e$$
 (5)

where  $\varkappa$  (  $\widetilde{\nu}$  ,  $\rho/\rho$  , T) is the linear absorption coefficient, can easily be obtained from the  $\,Q\,$  values through the relation:

(6)

Alternatively, the linear absorption coefficient can be found from the relation:

(7)

$$\kappa(\widetilde{v}, \frac{\rho}{\rho_0}, T) = 4.66 \times 10^{15} (\widetilde{v})^{-5} (e^{1.44 \widetilde{v}/T} - 1) Q(\widetilde{v}, \frac{\rho}{\rho_0}, T) cm^{-1}$$
.

#### USE OF THE TABLES

The values of  $Q(\heartsuit, \rho/\rho_0, T)$  which appear in the tables are the print-outs from an IBM 704 computer. The last two digits which appear in the numbers indicate powers of ten. For example, for  $T = 3000^\circ$ ,  $V = 1500 \text{ cm}^{-1}$ ,  $\rho/\rho_0 = 10^{-4}$ , the radiant emission is given as 0.91E - 08. The value, therefore, is 0.91 × 10<sup>-8</sup>.

#### REFERENCES

- 1. General Electric Company, Missile and Space Vehicle Department, Radiant Emission from High Temperature

  Equilibrium Air, R61SD 020, by R.G. Breene, Jr. and

  Maria Nardone, Philadelphia, Pa., May 1961.
- 2. The RAND Corporation, Equilibrium Composition and Thermodynamic Properties of Air to 24,000°K, RM-1543 by F.R. Gilmore, Santa Monica, California, August 1955.

TABLE I

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 3000°K

	T	1	<u> </u>
~ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	$\rho/\rho_{o} = 10^{-5}$	$\rho/\rho_{0} = 10^{-6}$
1250	0.36E-10	0.12E-11	0.40E-13
1500	0.91E-03	0.31E-09	0.40E 13
* *	0.59E-06	0.20E-07	0.65E-09
1750			
2000	0.86E-06	0.29E-07	0.94E-09
2250	0.20E-09	0.70E-11	0.22E-12
2500	0.	0.	0.
2750	0.45E-10	0.15E-11	0.50E-13
3000	0.14E-08	0.46E-10	0.15E-11
3250	0.29E-07	0.10E-08	0.32E-10
3500	0.36E-06	0.12E-07	0.40E-09
-3750	0.50E-06	0.17E-07	0.55E-09
4000	0.27E-08	0.93E-10	0.30E-11
4250	0.	0.	0.
4500	0.	0.	0.
4750	0.36E-10	0.12E-11	0.40E-13
5000	0.29E-07	0.99E-09	0.326-10
	0.91E-07 <	0.31E-08	<b>T</b>
5250			0.995-10
5500	0.91E-07	0.31E-08 .	0.99E-10
5750	0.43E-08	0.15E-09	0.47E-11
6000	0.36E-09	0.12E-10	0.40E-12
. 6250	σ.	U	0.
6500	0.	0.	• 0.
6750	0.	0.	0.
7000	0.	0.	0.
7250	0.	0.	0.
7500	0.	0.	0.
7.7750	0.	0.	0.
8000	0.	0.	0.
8250	0.	0.	0.
8500	0.	0.	0.
8750	0.	.0.	. 0.
9000	0.	. ŏ	0.
9250	0.	0.	ŏ.
	0.	δ	0.
9500			0.
9750	0.	0	· .
10000	0.	0.	0.
10250 .	0.	0.	0.
10500	0.	0.	0.
10750	0.	0.	0.
11000	0.	0.	0.
11250	0.	0.	0.
11500	. O	; 0.	. 0.
11750	0.	0.	0• '
12000	0.	0.	0.
		·	

TABLE I (Continued)
Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 3000°K

~ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	$\rho/\rho_{0} = 10^{-5}$	$\rho/\rho_{0} = 10^{-6}$
12250	0.	0.	0.
12500	0.	0.	0.
12750	0.	0.	0.
13000	0.	0.	0.
13250	0.	0.	0.
13500	0.	0.	0.
13750	0.	0.	0.
	0.	0.	0.
14000	0.	0.	0.
14250	0.	0.	0.
14500	0.	0.	0.
14750	0.	0.	-0
15000	0.	0.	. 0.
15250	0.	0.	0.
15500	o.	0.	0.
15750	ŏ. ···	0.	0.
16000	0.	0.	0.
16250	0.	0.	0
16500	0.	0.	0.
16750	0.	0.	0.
17000	0.	0.	0.
17250	-ō.	0.	0.
17500	0.	0.	0.
17750	0.	0.	0.
18000	0.	0.	0.
18250	0.	0.	0.
18500	0.	0.	0.
18750	ö.	0.	0.
19000	0.	0:	0.
19250	0.	0.	-0.
19500	0.	0.	0.
19750	0.16E-09	0.19É-11	0.20E-13
20000	0.75E-08	1	0.90E-12
20250	0.71E-08	0.88E-10	0.90E-12
20500	0.71E-08 0.65E-08	0.83E-10	0.78E-12
20750	0.61E-08	0.76E-10	0.78E-12
21000	0.61E-08	0.71E-10	
21250		0.71E-10	0.73E-12 0.68E-12
21500	0.57E-08	0.66E-10	
21750	0.10E-07 0.53E-08	0.12E-09	0.12E-11 0.63E-12
22000		0.62E-10	
22250	0.12E-07	0.14E-09	0.15E-11
22500	0.13E-07	0.15E-09	0.15E-11
22750	0.14E-07	0.17E-09	0.17E-11
_23000	0.18E-07	0.21E-09	0.22E-11

TABLE I (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 3000°K

~ (cm <sup>-1</sup> )	$\rho/\rho_{0} = 10^{-4}$	ρ/ρ <b>= 10<sup>-5</sup></b>	ρ/ρ = 10-6
23250	0.14E-07	0.17E-09	0.17E-11
23500	0.19E-07	0.22E-09	0.23E-11
23750	0.18E-07	0.21E-09	0.22E-11
24000	0.20E-07	0.24E-09	0.24E-11
24250	0.26E-07	0.31E-09	0.32E-11
24500	0.24E-07	0.28E-09	0.29E-11
24750	0.26E-07	0.31E-09	0.32E-11
25000	0.24E-07	0.28E-09	0.29E-11
25250	0.37E-07	0.44E-09	0.47E-11
<u> 25500</u>	0.41E-07	0.54E-09	0.76E-11
25750	0.45E-07	0.61E-09	0.93E-11
26000	0.32E-07	0.46E-09	0.74E-11
26250	0.36E-07	0.50E-09	0.76E-11
26500	0.44E-07	0.58E-09	0.84E-11
26750	0.56E-07	0.72E-09	0.96E-11
27000	0.64E-07	0.80E-09	0.10E-10
27250	0.45E-07	0.63E-09	0.98E-11
27500	0.495-07	0.68E-09	0.10E-10
27750	0.67E-07	0.91E-09	0.14E-10
28000	0.73E-07	0.91E-09	0.11E-10
28250	0.96E-07	0.12E-08	0.14E-10
28500	0.48E-07	0.65E-09	0.93E-11
. 28750	0.65E-07	0:87E-09	0.12E-10
29000	0.87E-07	0.12E-08	. 0.18E-10
. 29250	0.90E-07	0.13E-08 \	0.20E-10
29500	0.12E-06	0.17E-08	0.27E-10
29750	0.65E-07	0.83E-09	0.11E-10
30000	0.73E-07	0.95E-09	0.13E-10
30250	0.88E-07 .	0.11E-08	0.15E-10
30500	0.10E-06	0.14E-08	0.21E-10
30750	0.13E-06	0.18E-08	0.27E-10
31000	0.84E-07	0.13E-08	0.24E-10
31250	0.94E-07	0.13E-08	0.20E-10
31500	0.12E-06	0.16E-08	0.21E-10
31750	0.10E-06	0.14E-08	0.21E-10
32000	0.13E-06	0.17E-08	0.25E-10
32250	0.92E-07	0.13E-08	0.22E-10
32500 .	0.128-06	0.17E-08	0.28E-10
32750	0.16E-06	0.23E-08	0.38E-10
33000	0.10E-06	0.15E-08	0.23E-10
33250	0.13E-06	0.18E-08	0.29E-10
33500	0.12E-06	0.20E-98	0.39E-10
33750	0.13E-06	0.21E-08	0.41E-10
34000	0.18E-06	0.29E-08	0.58E-10

TABLE I (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 3000°K

~ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	$\rho/\rho_{o} = 10^{-5}$	$\rho/\rho_{0} = 10^{-6}$
34250	0.13E-06	0.22E-08	0.45E-10
34500	0.16E-06	0.26E-08	0.52E-10
34750	0.18E-06	0.26E-08	0.44E-10
35000	0-15E-06	0.28E-08	0.62E-10
35250	0.206-06	0.36E-08	0.80E-10
35500	0.18E-06	0.31E-08	0.65E-10
35750	0.18E-06	0.33E-08	0.74E-10
36000	0.19E-06	0.31E-08	0.59E-10
36250	0.14E-06	0.25E-08	0.55E-10
36500	0.15E-06	0.23E-08	0.43E-10
36750	0.19E-06	0.31E-08	0.63E-10 .
37000	0.176-06	0.38E-08	0.10E-09
37250	0.15E-06	0-28E-08	0.62E-10
37500	0.18E-06	0.35E-08	0.82E-10
37750	0.88E-07	0.20E-08	0.53E-10
38000	0.10E-06	0.21E-08	0.51E-10
38250	0.30E-07	0.10E-08	0.33E-10
38500 ·	0.27E-07	0.93E-09	0.30E-10
38750	0.15E-06	0.51E-08	0.16E-09
39000	0.86E-07	0.29E-08	0.94E-10
39250	0.71E-07	0.24E-08	0.78E-10
39500	0.506-07	0.17E-08	0.55E-10 0.39E-10
39750	0.35E-07 '0.27E-07	0.12E-08 0.93E-09	0.30E-10
40000	0.27E-07	0.93E-09 0.51E-09	0.30E-10 0.16E-10
40250	0.19E-06	0.66E-08	0.18E-10
40500	0.11E-06	0.37E-08	0.12E-09
40750	0.68E-07	0.23E-08	0.75E-10
41000	0.46E-07	0.16E-08	0.51E-10
41250	0.40E-07	-0.98E-09	0.31E-10
41500	0.23E-07	0.79E-09	0.25E-10
41750 42000	0.14E-07	0.48E-09	0.15E-10
42250	0.19E-06	0.64E-08	0.21E-09
42500 42500	0.21E-06	0.71E-08	0.23E-09
42750	0.10E-06	0.36E-08	0.11E-09
43000	0.54E-07	0.19E-08	0.60E-10
43250	0.40E-07	0.14E-08	0.44E-10
43500	0.31E-07	.0.11E-08	0.34E-10
43750	0.23E-07	0.77E-09	0.25E-10
44000	0.13E-07	0.45E-09	0.15E-10
44250	0.29E-06	0.98E-08	0.31E-09
44500	0.15E-06	0.51E-08	0.16E-09
44750	0.13E-06	0.46E-08	0.15E-09
45000	0.87E-07	0.30E-08	0.95E-10

TABLE I (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 3000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ=10 <sup>-5</sup>	$\rho/\rho_{0} = 10^{-6}$
45250	0.72E-07	0.25E-08	0.80E-10
45500	0.54E-07	0.18E-08	0.59E-10
45750	0.38E-07	0-13E-08 :	0.41E-10
46000	0.31E-07	0.10E-08	0.33E-10
46250	0.29E-07	1.00E-09	0.32E-10
46500	0.77E-07	0.26E-08	0.84E-10
46750	0.13E-06	0.46E-08	0.15E-09
47000	0.68E-07	0.23E-08	0.75E-10
47250	0.45E-07	0.15E-08 ·	0.49E-10
47500	70.34E-07	_0:11E=08_	0.37E-10
47750	0.19E-07	0.65E-09	0.21E-10
48000	0.17E-07	0.59E-09	0.19E-10
48250	0.18E-07	0.60E-09	0.19E-10
4,8500	0.14E-07	0.486-09	0.15E-10
48750	0.20E-07	0.68E-09	0.22E-10
, 49000	0.62E-07	0.21E-08	0.68E-10
49250	0.58E-07	0.205-08	0.64E-10
49500	0.34E-07	0.12E-08	0.37E-10
49750	0-21E-07	0.71E-09	0.23E-10
50000	0.15E-07	0.53E-09	0.17E-10
50250	0.14E-07	0.50E-09	0.16E-10
50500	0.535-08	0-18E-09	0.59E-11
50750	0.48E+08	0.17E-09	0.53E-11
51000	0.24E-07	0.84E-09	0.27E-10
51250	0.26E-07	0.90E-09	0.29E-10
51500	0.25E-07	0.85E-09	0.27E-10
51750	0.14E-07 0.91E-08	0.48E-09	0.15E-10
52000	0.63E-08	0.31E-09 0.22E-09	0.99E-11 0.70E-11
52250	0.32E-08	0.22E-09	0.70E-11 0.35E-11
52500 52750	0.34E-08	0.11E-09	0.37E-11
53000	0.37E-08	0.13E-09	0.41E-11
53250 ·	0.54E-08	0.18E-09	0.59E-11
53500	0.77E-08	0.26E-09	0.84E-11
53750	0.95E-08	0.33E-09	0.10E-10
54000	0.90E-08	0.31E-09	0.99E-11
54250	0.39E-08	0.13E-09	0.43E-11
54500	0.43E-08	0.15E-09	0.47E-11
54750	0.46E-08	0.16E-09	0.50E-11
55000	0.34E-08	0.12E-09	0.38E-11
55250	0.27E-08	0.91E-10	0.29E-11
55500	0.34E-08	0.11E-09	0.37E-11
55750	0.39E-08	0.13E-09	0.42E-11
56000	0.18E-08	0.62E-10	0.20E-11

TABLE II

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 4000°K

⊽ (cm <sup>-1</sup> )	$\rho/\rho_o = 10^{-4}$	ρ/ρ <b>= 10<sup>-5</sup></b>	ρ/ρ <sub>o</sub> = 10-6
1250 1500 1750 2000 2250 2500 2750 3000 3250 3500 3750 4000 4250 4500 4750 5000 5250 5500 5750 6000 6250 6500 6750 7000 7750 8000 8250 8500 8750 9000 9250 9500 9750 10000 10250 10500 10750 11000 11250 11750 11750 11750	0. 0.13F-07 0.19E-06 0.26E-06 0.22E+08 0. 0.16E-08 0.30E-07 0.19E-06 0.19E-06 0.26E-09 0.26E-09 0.22E-08 0.19E-07 0.38E-07 0.48E-07 0.13E-07 0.17E-08 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.	0. 0.40E-09 0.57E-08 0.79E-08 0.69E-10 0. 0. 0.49E-10 0.92E-09 0.59E-08 0.79E-11 0.69E-10 0.59E-09 0.12E-08 0.15E-08 0.17E-08 0.40E-09 0.52E-10 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.	0. 0.11E-10 0.17E-09 0.23E-09 0.20E-11 0. 0.14E-11 0.27E-10 0.17E-09 0.17E-09 0.23E-12 0.23E-12 0.20E-11 0.17E-10 0.34E-10 0.49E-10 0.15E-11 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0. 0.

TABLE II (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 4000°K

<b>⊽</b> (cm <sup>-1</sup> )	ρ/ρ <sub>0</sub> = 10 <sup>-4</sup>	ρ/ρ= 10-5	p/p <sub>o</sub> = 10-6
12250	0.	0.	0.
12500	Ó.	0.	0.
12750	0.	0.	0.
13000	δ.	0.	0.
13250	0.	0.	0.
13500	0.	0.	. 0.
13750.	<sup>1</sup> 0. <b>.</b>	0.	0-
14000	0.	0.	Õ.
14250	0.	0.	0.
14500	0.	0.	0,
14750	0.	0.	Ó.
15000	0.	0.	0
15250	0.	Ō.	0.
15500	0.	0.	0.
. 15750	0.	0.	0.
16000	0.	0.	0.
16250	0.	0.	0.
16500	0.	0.	0.
16750	0.	0.	0.
17000	0.	0.	0.
17250	0.	0.	0.
17500	0.	0.	0.
17750	0.	0.	, O.
18000	0.	0.	0.
18250	0.	0.	0.
18500	0.	0.	. 0.
18750	. 0.	0.	0.
19000	0.	0.	0.
19250	0.	0.	0.
19500	0.	0.	0.
19750	0.	0.	0.
20000	0.	0.	0.
20250	0.	0.	0.
20500	0.	. 0.	0.
20750	0.	0.	0.
21000	0.40=-07	0.40E-09	0.40E-11
21250	0.40E-07	0.40E-09	0-40E-11
21500	0.37E-07	0.38E-09	0.38E-11
21750	0.36E-07	0.37E-09	0.37E-11
22000	0.34E-07	0.35E-09	0.35E-11
22250	0.67E-07	0.67E-09	0.67E-11
22500	0.13E-06	0.33E-08	0.89E-10
22750	0.13E-06	0.33E-08	0.89E-10
23000	0.16E-06	Q.36E-08	0.92E-10

TABLE II (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 4000°K

ν̃ (cm <sup>-1</sup> )	p/p <sub>o</sub> = 10 <sup>-4</sup>	ρ/ρ=10 <sup>-5</sup>	p/p = 10-6
23250	0.13E-06	0.33E-08	
23500	0.14E-06	0.34E-08	0.88E-10
23750	0.14E-06	0.33E-08	0.86E-10
24000	0.14E-06	0.32E-08	0.83E-10
24250	0.19E-06	0.46E-08	0.12E-09
24500	0.15E-06	0.32E-08	0.79E-10
24750	0.19E-06	0.43E-08	0.11E-09
<u>25000</u> 25250	0.14E-06 0.23E-06	0.30E-08	0.73E-10
25500	0.29E-06	0.51E-08	0.13E-09
25750 25750	0.29E-06	0.69E-08	0.18E-09 0.18E-09
26000	0.26E-06	0.63E~08	0.18E-09
<u>26250</u>	0.33E-06	0.80E-08	0.21E-09
26500	0.24E-06	0.51E-08	0.13E-09
26750	0.29E-06	0.61E-08	0.15E-09
27000	0.43E-06	0.94E-08	. 0.24E-09
27250	0.38E-06	0.98E-08	0.26E-09
_27500	0.39E-06	0.95E-08	0.25E-09
27750	0.49E-06	0.12E-07	0.30E-09
28000	0.33E-06	0.60E-08	0.13E-09
28250	0.45E-06	0.92E-08	0.22E-09
<u> 28500</u>	0.40E-06	0.95E-08	0.25E-09
28750	0.54E-06	0.13E-07	0.33E-09
, 29000	0.72E-06	0.15E-07	0.38E-09
29250	0.73E-06	0.18E-07	0.48E-09
<u>29500</u>	0.84E-06	10.20E-07	0.52E-09
29750	0.44E-06 0.50E-06	0.98E-08 _	0.25E-09 0.28E-09
30000	0.55E-06	0.11E-07	0.28E-09
30 <u>250</u> 30500	0.77E-06	0.12E-07 0.18E-07	0.49E-09
30750	0.11E-05	0.18E-07	0.75E-09
31000	0.11E-05	0.31E-07	0.85E-09
31250	0.91E-06	0.23E-07	0.60E-09
31500 -	0.89E-06	0.21E-07	0.55E-09
31750	0.97E-06	0.24E-07	0.65E-09
32000	0.10E-05	0.25E-07	0.66E-09
32250	0.93E-06	0.24E-07	0.64E-09
32500	0.12E-05	0.30E-07_	0.81E-09
32750	0.14E-05	0.34E-07	0.91E-09
33000	0.86E-06	0.21E-07	0.56E-09
33250	0.12E-05	0.29E-07	0.78E-09
33500	0.13E-05	0.35E-07_	0.95E-09
33750	0.13E-05	0.34E-07	0.94E-09
34000	0.20E-05	0.53E-07	0.15E-08

TABLE II (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 4000°K

⊽ (cm <sup>-1</sup> )	ρ/ρ <sub>ο</sub> = 10 <sup>-4</sup>	ρ/ρ= 10 <sup>-5</sup>	ρ/ρ = 10-6
34250	0.16E-05	0.45E-07	0.12E-08
34500	0.19E-05	0.52E-07	0.14E-08
34750	0.17E-05	0.43E-07	0.12E-08
35000	0.22E-05	0-62E-07	0.17E-08
35250	0.28E-05	0.78E-07	0-22E-08
35500	0.24E-05	0.67E÷07	0.19E-08
35750	0.29E-05	0.81E-07	0.23E-08
36000	0.23E-05	0.64E-07	0.18E-08
36250	0.23E-05 0.19E-05	0.65E-07	0.18E-08 "0.15E-08
36500	0.19E-05	0.53E-07 0.69E-07	0.19E-08
_36750	0.23E-05	0.89E-07 0.11E-06	0.31E-08
37000	0.37E-05	0.11E-08	· 0 • 24E-08
37250	0.35E-05	0.10E-06	0.29E-08
37500	0.35E-05	0.75E-07	0.21E-08
37750 38000	0.23E-05	0.70E-07	0.20E-08
382 <u>50</u>	0.19E-05	0.59E-07	0.17E-08
38500	0.19E-05	0.57E-07	0.17E-08
38750	0650E-05	0.15E-06	0.45E-08
39000	0.38E-05	0.12E-06	0.34E-08
39250	0.37E-05	0.11E-06	0.33E-08
39500	0.28E-05	. 0.87E-07	0.25E-08
39750	0.22E-05	0.68E-07	0.20E-08
· 40000	0.18E-05	.0.56E-07	0.16E-08
40250	0.12E-05	0.37E-07	0.11E+08
40500.	0.64E-05	_0.20E-06_	0.58E-08
40750	0.41E-05	0.13E-06	0.37E-08
41000	0.37E-05	.0 • 12E-06	0.34E-08
41250	0.25E-05	0.78E-07	0.23E-08
41500	0.18E-05	0.54E-07	0.16E-08 0.14E-08
41750	0-15E-05 0-96E-06	0.48E-07 0.30E-07	0.86E-09
42000	0.38E-05	0.12E-06	0.34E-08
42250	0.38E-03	0.12E-06 0.25E-06_	0.72E-08
42500	0.53E-05	0-16E-06	0.48E-08
42750	0.31E-05	0.97E-07	0.28E-08
43000 43250	0.25E-05	0.76E-07	· 0.22E-08
43500	0.19E-05	0.59E-07_	0.17E-08
43750	0.16E-05	0.49E-07	0.14E-08
44000	0.96E-06	0.30E-07	0.86E-09
44250	0.10E-04	0.32E-06	· 0 • 94E-08
44500	0.60E-05	0.19E-06	0.54E-08
44750	0.59E-05	0.18E-06	0.53E-08
45000	0.45E-05	0.14E-06	0.41E-08

TABLE II (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 4000°K

ີ ິ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ= 10 <sup>-5</sup>	ρ/ρ <sub>0</sub> # 10-6
<u> 45250</u>	0.39E-05	0.12E-06	1 0.35E-08 !
45500	0.31E-05	0.95E-07	0.28E-08
45750	0.23E-05	0.70E-07	0.20E-08
4,6000	0.18E-05	0.54E-07	0.16E-08
46250	0.16E-05	0.49E-07	0.14E-08
46500	0.33E-05	0.10E-06	0.29E-08
46750	0.69E-05	_0.21E-06_	0.62E-08
47000	0.42E-05	0.13E-06	0.38E-08
47250	0.31E-05	0.96E-07	0-28E-08
47500	0.25E-05	0.78E-07	0.23E-08
47750	0.16E-05	_0.49E-07_	0-14E-08
48000	0.13E-05	0.40E-07	0.11E-08
48250	0.13E-05	_0.41E-07_	0.12E-08
48500	0.11E-05	0.33E-07	0.95E-09
48750	0.18E-05	_0.56E-07_	0-16E-08
49000	0.47E-05	0.15E-06	0.42E-08
49250	0.42E-05	_0.13E-06_	0.38E-08
49500	0.29E-05	0.91E-07	0.26E-08
49750	0.20E-05	_0.61E-07_	0.18E-08
50000	0.16E-05	0.49E-07	0.14E-08
50250	0.13E-05	_0.40E-07_	0.11E-08
50500	0.56E-06	0.17E-07	0.50E-09
50750	0.57E-06	_0.18E-07_	0.51E-09
, 51000	0.18E-05	0.54E-07	0.16E-08
51250	0-21E-05	_0.64E-07	0.19E-08
51500	0.25E-05	0.78E-07	0.23E-08
51750	0.16E-05	_0.49E-07	0.14E-08
<u> 52000</u>	0.11E-05	0.36E-07	0.10E-08
52250	0-83E-06	_0.26E-07	0.75E-09
52500	0.48E-06	0.15E-07	0.43E-09
52750	0.48E-06	_0.15E-07_	0.43E-09
<u>53000</u>	0.48E-06	0.15E-07	0.43E-09
53250	0.77E-06	_0.24E-07_	0.69E-09
<u>53500</u>	0.96E-06	0.30E-07	0.86E-09
5375 <del>0</del>	0.12E-05	_0.38E-07_	0.11E-08
54000	0.97E-06	0.30E-07	0-87E-09
, <b>5425</b> 0.	0.57E-06	_0.18E-07_	0.52E-09
<u>54500</u>	0.60E-06	0.19E-07	0.54E-09
54750	0.67E-06	0.21E-07 0.14E-07	0.60E-09
55000	0.46E-06		0.41E-09
55250	0.39E-06	_0.12E-07_	0+35E-09
<u>55500</u>	0.51E-06	0.16E-07 	0.46E-09
55750	0.54E-06	0.86E-08	0.49E-09 0.25E-09
56000	0.28E-06	0.00E-00	ひ・と ノモー リガ

TABLE III

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 5000°K

♥ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <sub>o</sub> = 10 <sup>-5</sup>	p/p <sub>o</sub> = 10-6
1250	Ô.	0.	0.
1500	0.14E-07	0.30E-09	0.39E-11
1750	0.75E-07	0.15E-08	0.20E-10
2000	0.11E-06	0.23E-08	0.30E-10 0.50E-11
2250	0.18E-07 0.28E-08	0.38E-09 0.57E-10	0.75E-12
2750	0.202 00	0.5/2-10	. 0.
3000	0.83E-08	0.17E-09_	0.23E-11
3250	0.44E-07	0.91E-09	0.12E-10
3500	0.10E-06	0.22E-08	0.29E-10
3750	0.83E-07	0.17E-08	0.23E-10
4000	0.11E-07	0.23E-09	0.30E-11
4250	0.	0.	0.
4500	0.	0	0.
4750	0.13E-06	0.54E-08	0.93E-10
5000	0.14E-06	0.60E-08	0.10E-09 0.11E-09
5250 5500	0.15E-06 0.17E-06	0.64E-08 0.73E-08	0.11E-09
5750	0.41E-06	0.13E-08_ 0.17E-07	0.30E-09
-6000	0.30E-06	0.13E-07	0.22E-09
6250	0.45E-06	0.19E-07	0.33E-09
6500	0.37E-06	0.16E-07_	0.27E-09
6750	0.52E-06	0.22E-07	0.38E-09
7000	0.12E-05	0.51E-07_	0.88E-09
7250	0.16E-05	0.70E-07	0.12E-08
, 7500	0.14E-05	0.60E-07	0.10E-08
7750	0.90E-06	0.38E-07	0.66E-09
8000	0.49E-06	_0.21E-07_	0.36E-09 0.44E-08
8250	0.60E-05 0.50E-05	0.25E-06 _0.21E-06_	0.44E-08
8500 8750	0.43E-05	0.18E-06	0.37E 00
9000	0.25E-05	_0.11E-06_	0.19E-08
9250	0.20E-05	0.86E-07	0.15E-08
9500	0.16E-05	_0.70E-07	0.12E-08
9750	0.13E-04 :	0.57E-06	0.99E-08
10000	0.73E-05	_0.31E-06	0.54E-08
10250	0.75E-05	0.32E-06	0.55E-08
10500	0.61E-05	_0.26E-06	0.45E-08
10750	0.52E-05	0.22E-06	0.38E-08
11000	0.30E-05	_0.13E-06	0.22E-08 0.27E-08
11250	0.37E-05 0.22E-04	0.16E-06	0.27E-08
11500	0.22E-04 0.15E-04	0.95E-06 0.64E-06	0.11E-07
<u>11750</u> .	0.13E-04 0.82E-05	0.84E-08 0.35E-06_	0.60E-08
12000	U O E CEE GO	V.JJE-00_	

TABLE III (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 5000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_0 \approx 10^{-4}$	ρ/ρ = 10 <sup>-5</sup>	p/p = 10-6
	. 0		0
12250	0.55E-05	0.23E-06	0.40E-08
12500	0.41E-05	0.17E-06	0.30E-08
12750	: 0.36E-05	0.15E-06	0.26E-08
13000	0.63E-05	0.27E-06	0.47E-08
13250	0.20E-04	0-86E-06 .	0.15E-07
13500	0.16E-04	0.67E-06	0.12E-07
_13750	0.11E-04	0.48E-06	0.82E-08
14000	0.67E-05	0.29E-06	0.49E-08
14250	0.37E-05	0.16E-06	0.27E-08
14500	0.15E-05	0.64E-07	0.11E-08
14750	0.37E-05	_0.16E-06	0.27E-08
15000	0.67E-05	-0.29E-06	0.49E-08
15250	0.75E-05	0.32E-06	0.55E-08
15500	0.75E-05	0.32E-06	0.55E-08
15750	0.52E-05	0.22E-06	0.38E-08
16000	0.450-05	0.19E-06	0.33E-08
16250	0.15E-05	0.64E-07	0.11E-08
16500	0.26E-05	0.11E-06	0.19E-08
16750	0.22E-05	0.95E-07	0.16E-08
17000	0.30E-05	0.13E-06	0.22E-08
17250	0.34E-05	0.14E-06	0.25E-08
17500	0.22E-05	0.95E-07 0.64E-07	0.16E-08
17750	0.15E-05 0.15E-05	0.64E-07	0.11E-08
18000		0.64E-07	0-11E-08
18250	0.15E-05 0.15E-05	0.64E-07	0.11E-08 0.11E-08
18500	0.15E-05	0.64E-07	0.11E-08
18750	0.15E-05	0.64E-07	0.11E-08
19000 19250	0.14E-05	0.60E-07	0.11E-08
19500	0.14E-05	0.60E-07	0.10E-08
19750	0.14E-05	0.60E-07	0.10E-08
20000	0.14E-05	0.60E-07	0.10E-08
20250	0.14E-05	0.60E-07	0.10E-08
20500	0.14E-05	0.60E-07	0.10E-08
20750	0.14E-05	0.60E-07	0.10E-08
21000	0.14E-05	0.60E-07	0.10E-08
21250	0.14E-05	0.60E-07	0.10E-08
21500	0.14E-05	0.60E-07	0.10E-08
21750	0.66E-06	0.12E-07	0.15E-09
22000	0.66E-06	0.12E-07	0.15E-09
22250	0.60E-06	0.11E-07	0.14E-09
22500	0.60E-06	0.11E-07	0.14E-09
22750	0.65E-06	0.12E-07	0.16E-09
23000	0.65E-06	0.12E-07	0.16E-09
		l	<u> </u>

TABLE III (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 5000°K

♡ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	$\rho/\rho_{0} = 10^{-5}$	ρ/ρ = 10-6
23250	0.65E-06	0.12E-07	0.16E-09
23500	0.18E-05	0.20E-05	0.16E-06
23750	0.16E-05	0.17E-05	• 0.13E-06
24000	0.15E-05	0.11E-05	0.87E-07
24250 <sup>-</sup>	0.18E-05	0.18E-05	0.14E-06
24500	0.14E-05	0.13E-05	0.10E-06 0.61E-07
24750	0.15E-05 0.12E-05	0.79E-06	0.31E-09
25000 25250	0.12E-05 0.17E-05	0.23E-07	0.31E-09 0.10E-06
25500	0.17E-05	0.13E-05_ 0.22E-05	0.17E-06
25750 25750	0.52E-05	0.88E-05_	0.69E-06
26000	0.30E-05	0.88E-05	0.30E-06
26250	0.24E-05	0.14E-05_	0.10E-06
26500	0.20E-05	0.15E-05	0.11E-06
26750	0.24E-05	.0.17E-05	0.13E-06
27000	0.25E-05	0.59E-06	0.44E-07
27250	0.27E-05	0.53E-07	0.70E-09
27500	0.24E-05	0.48E-07	0.62E-09
27750	0-33E-05	0.65E-07	0.85E-09
28000	0.44E-05	0.37E-05	0.29E-06
28250	0.61E-05	.0.50E-05	0.39E-06
28500	0.53E-05	0.21E-05	0.16E-06
28750	0.51E-05	0.11E-05.	0.78E-07
· . <u>29000</u>	0.53E-05	0.11E-06;	0.14E-08
29250	0.56E-05	0.11E-06_	0.15E-08
29500	0.59E-05	0.12E-06	0.15E-08
29750	0.51E-05	_0.14E-06_	0.20E-08 0.14E-08
30000	0.42E-05	0.97E-07	,
30250	0.51E-05 0.57E-05	0.11E-06_	0.16E-08 0.64E-07
30500. 30750.	0.63E-05	_0.90E-06_	0.62E-07
31000	0.64E-05	0.89E-06 _0.13E-06;	0.02E-07
31250	0.51E-05	0.10E-06	0.13E-08
31500	0.41E-05	_0.79E-07	0.10E-08
31750	0.59E-05	0.14E-06	0.20E-08
32000	0.64E-05	0.15E-06	0.21E-08
32250	0.64E-05	0.14E-06	0.19E-08
32500	0.69E-05	0.14E-06	0.18E-08
32750	0.79E-05	0.16E-06	0.21E-08
33000	0.56E-05	_0.11E-06_	0-14E-08
33250	0.66E-05	0.13E-06	0.17E-08
33500	0.87E-05	0-17E-06_	0.23E-08
33750	0.80E-05	0.16E-06	0.21E-08
34000	0.12E-04	_0.25E-06	0.32E-08

TABLE III (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 5000°K

⊽ (cm <sup>-1</sup> )	ρ/ρ = 10 <sup>-4</sup>	ρ/ρ <mark>= 10<sup>-5</sup></mark>	ρ/ρ = 10-6
34250	~ 0.11E-04	0.22E-06	0.28E-08
34500	0.12E-04	0.25E-06	0.33E-08
34750	0.11E-04	0.23E-06	0.30E-08
35000	0.15E-04	0.30E-06	0.40E-08
35250	0.18E-04 0.16E-04	0.36E-06 0.32E-06	0.48E-08 0.43E-08
35500	0.16E-04 0.20E-04	0.32E-06 0.40E-06	0.53E-08
35750 36000	0.20E-04	0.40E-06	0.43E-08
36250	0.13E-04	0.35E-06	0.46E-08
36500	0.17E-04	0.30E-06	0.40E-08
36750	0.18E-04	0.36E-06	0.48E-08
37000	0.25E-04	0.52E-06	0.68E-08
37250	0.20E-04	0.41E-06	0.54E-08
37500	0.25E-04	0.52E-06	0.68E-08
37750	0.20E-04	0.41E-06	0.54E-08
38000	0.19E-04	0.39E-06	0.52E-08.
38250	0.17E-04	0.35E-06	0-46E-08
38500	0.16E-04	0.32E-06	0.43E-08
38750	0.35E-04	0.72E-06	0.95E-08 :
39000	0.28E-04	0.57E-06	0.75E-08
39250	0.29E-04	0-59E-06	0.78E-08
39500	0.23E-04	0.48E-06	0.63E-08
39750	0.19E-04	0.39E-06	0.51E-08
. 40000	0.16E-04	0.33E-06	0.44E-08
40250	0.12E-04	0.24E-06	0.32E-08
40500	0.34E-04	0.69E-06	0.92E-08
40750	0.33E-04	0.67E-06	0.89E-08
41000	0.29E-04	0.60E-06	0.80E-08
41250	0.21E-04	0.44E-06	0.58E-08
41500	0.16E-04	0.34E-06	0.44E-08
41750	0.14E-04	0.30E-06	0.39E-08 0.29E-08
42000	0.10E-04	0-22E-06	0.29E-08
42250	0.39E-04 0.57E-04	0-81E-06 0-12E-05	0.11E-07
42500	0.37E-04 0.35E-04	0.73E-06	0.96E-08
<u>42750</u> 43000	0.25E-04	0.51E-06	0.68E-08
43250	0.21E-04	0.44E-06	0.58E-08
43500	0.21E-04	0.36E-06	0.48E-08
43750	0.16E-04	0.32E-06	0.43E-08
44000	0.11E-04	0.23E-06	0.30E-08
44250	0.69E-04	0.14E-05	0.19E-07
44500	0.43E-04	0.88E-06	0.12E-07
44750	0.44E-04	0.91E-06	· 0.12E-07
45000	0.38E-04	0.79E-06	0.10E-07

TABLE III (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 5000°K

45250       0.34E-04       0.71E-04       0.93E-08         45500       0.27E-04       0.56E-06       0.74E-08         45 50       0.22E-04       0.46E-06       0.60E-08         46000       0.17E-04       0.35E-06       0.46E-08         46250       0.15E-04       0.31E-06       0.41E-08         46500       0.29E-04       0.60E-06       0.79E-08         46750       0.55E-04       0.11E-05       0.15E-07         47000       0.43E-04       0.89E-06       0.12E-07         47500       0.28E-04       0.58E-06       0.77E-08         47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.48E-08         48250       0.14E-04       0.28E-06       0.38E-08         48750       0.30E-04       0.61E-06       0.80E-08         48750       0.39E-04       0.61E-06       0.47E-08         49250       0.38E-04       0.67E-06       0.1E-07         49500       0.32E-04       0.67E-06       0.67E-08         49750       0.25E-04       0.51E-06       0.67E-08         50250       0.17E-04       0.39E-06       0.52E-08
45500       0.27E-04       0.56E-06       0.74E-08         45 50       0.22E-04       0.46E-06       0.60E-08         46000       0.17E-04       0.35E-06       0.46E-08         46250       0.15E-04       0.31E-06       0.41E-08         46500       0.29E-04       0.60E-06       0.79E-03         46750       0.55E-04       0.11E-05       0.15E-07         47000       0.43E-04       0.89E-06       0.77E-08         47500       0.28E-04       0.58E-06       0.77E-08         47500       0.25E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48500       0.30E-04       0.61E-06       0.80E-08         48750       0.35E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.1E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08
45 50         0.22E-04         0.46E-06         0.60E-08           46000         0.17E-04         0.35E-06         0.46E-08           46250         0.15E-04         0.31E-06         0.41E-08           46500         0.29E-04         0.60E-06         0.79E-08           46750         0.55E-04         0.11E-05         0.15E-07           47000         0.43E-04         0.89E-06         0.12E-07           47250         0.28E-04         0.58E-06         0.77E-08           47500         0.25E-04         0.52E-06         0.68E-08           47750         0.18E-04         0.36E-06         0.48E-08           48000         0.15E-04         0.30E-06         0.40E-08           48250         0.14E-04         0.28E-06         0.38E-08           48750         0.17E-04         0.35E-06         0.47E-08           49000         0.39E-04         0.81E-06         0.11E-07           49250         0.38E-04         0.78E-06         0.10E-07           49500         0.32E-04         0.67E-06         0.67E-08           49750         0.32E-04         0.51E-06         0.67E-08           50000         0.19E-04         0.39E-06         0.52E-08
46000       0.17E-04       0.35E-06       0.46E-08         46250       0.15E-04       0.31E-06       0.41E-08         46500       0.29E-04       0.60E-06       0.79E-08         46750       0.55E-04       0.11E-05       0.15E-07         47000       0.43E-04       0.89E-06       0.12E-07         47250       0.28E-04       0.58E-06       0.77E-08         47500       0.25E-04       0.52E-06       0.68E-08         47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.39E-06       0.45E-08
46250       0.15E-04       0.31E-06       0.41E-08         46500       0.29E-04       0.60E-06       0.79E-08         46750       0.55E-04       0.11E-05       0.15E-07         47000       0.43E-04       0.89E-06       0.12E-07         47250       0.28E-04       0.58E-06       0.77E-08         47500       0.25E-04       0.52E-06       0.68E-08         47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48750       0.30E-04       0.61E-06       0.80E-08         49000       0.39E-04       0.35E-06       0.47E-08         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
46500       0.29E-04       0.60E-06       0.79E-08         46750       0.55E-04       0.11E-05       0.15E-07         47000       0.43E-04       0.89E-06       0.12E-07         47250       0.28E-04       0.58E-06       0.77E-08         47500       0.25E-04       0.52E-06       0.68E-08         47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48500       0.30E-04       0.61E-06       0.80E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
46750         0.55E-04         0.11E-05         0.15E-07           47000         0.43E-04         0.89E-06         0.12E-07           47250         0.28E-04         0.58E-06         0.77E-08           47500         0.25E-04         0.52E-06         0.68E-08           47750         0.18E-04         0.36E-06         0.48E-08           48000         0.15E-04         0.30E-06         0.40E-08           48250         0.14E-04         0.28E-06         0.38E-08           48500         0.30E-04         0.61E-06         0.80E-08           48750         0.17E-04         0.35E-06         0.47E-08           49000         0.39E-04         0.81E-06         0.11E-07           49250         0.38E-04         0.78E-06         0.10E-07           49500         0.32E-04         0.67E-06         0.67E-08           49750         0.25E-04         0.51E-06         0.67E-08           50000         0.19E-04         0.39E-06         0.52E-08           50250         0.17E-04         0.34E-06         0.45E-08
47000       0.43E-04       0.89E-06       0.12E-07         47250       0.28E-04       0.58E-06       0.77E-08         47500       0.25E-04       0.52E-06       0.68E-08         47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48500       0.30E-04       0.61E-06       0.80E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
47250       0.28E-04       0.58E-06       0.77E-08         47500       0.25E-04       0.52E-06       0.68E-08         47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48500       0.30E-04       0.61E-06       0.80E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.67E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
47500         0.25E-04         0.52E-06         0.68E-08           47750         0.18E-04         0.36E-06         0.48E-08           48000         0.15E-04         0.30E-06         0.40E-08           48250         0.14E-04         0.28E-06         0.38E-08           48500         0.30E-04         0.61E-06         0.80E-08           48750         0.17E-04         0.35E-06         0.47E-08           49000         0.39E-04         0.81E-06         0.11E-07           49250         0.38E-04         0.78E-06         0.10E-07           49500         0.32E-04         0.67E-06         0.67E-08           49750         0.25E-04         0.51E-06         0.67E-08           50000         0.19E-04         0.39E-06         0.52E-08           50250         0.17E-04         0.34E-06         0.45E-08
47750       0.18E-04       0.36E-06       0.48E-08         48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48500       0.30E-04       0.61E-06       0.80E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
48000       0.15E-04       0.30E-06       0.40E-08         48250       0.14E-04       0.28E-06       0.38E-08         48500       0.30E-04       0.61E-06       0.80E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
48250         0.14E-04         0.28E-06         0.38E-08           48500         0.30E-04         0.61E-06         0.80E-08           48750         0.17E-04         0.35E-06         0.47E-08           49000         0.39E-04         0.81E-06         0.11E-07           49250         0.38E-04         0.78E-06         0.10E-07           49500         0.32E-04         0.67E-06         0.88E-08           49750         0.25E-04         0.51E-06         0.67E-08           50000         0.19E-04         0.39E-06         0.52E-08           50250         0.17E-04         0.34E-06         0.45E-08
48500       0.30E-04       0.61E-06       0.80E-08         48750       0.17E-04       0.35E-06       0.47E-08         49000       0.39E-04       0.81E-06       0.11E-07         49250       0.38E-04       0.78E-06       0.10E-07         49500       0.32E-04       0.67E-06       0.88E-08         49750       0.25E-04       0.51E-06       0.67E-08         50000       0.19E-04       0.39E-06       0.52E-08         50250       0.17E-04       0.34E-06       0.45E-08
48750     0.17E-04     0.35E-06     0.47E-08       49000     0.39E-04     0.81E-06     0.11E-07       49250     0.38E-04     0.78E-06     0.10E-07       49500     0.32E-04     0.67E-06     0.88E-08       49750     0.25E-04     0.51E-06     0.67E-08       50000     0.19E-04     0.39E-06     0.52E-08       50250     0.17E-04     0.34E-06     0.45E-08
49000     0.39E-04     0.81E-06     0.11E-07       49250     0.38E-04     0.78E-06     0.10E-07       49500     0.32E-04     0.67E-06     0.88E-08       49750     0.25E-04     0.51E-06     0.67E-08       50000     0.19E-04     0.39E-06     0.52E-08       50250     0.17E-04     0.34E-06     0.45E-08
49250     0.38E-04     0.78E-06     0.10E-07       49500     0.32E-04     0.67E-06     0.88E-08       49750     0.25E-04     0.51E-06     0.67E-08       50000     0.19E-04     0.39E-06     0.52E-08       50250     0.17E-04     0.34E-06     0.45E-08
49500     0.32E-04     0.67E-06     0.88E-08       49750     0.25E-04     0.51E-06     0.67E-08       50000     0.19E-04     0.39E-06     0.52E-08       50250     0.17E-04     0.34E-06     0.45E-08
49750     0.25E-04     0.51E-06     0.67E-08       50000     0.19E-04     0.39E-06     0.52E-08       50250     0.17E-04     0.34E-06     0.45E-08
50000 0.19E-04 0.39E-06 0.52E-08 50250 0.17E-04 0.34E-06 0.45E-08
50250 0.17E-04 0.34E-06 0.45E-08
The second of th
50750 0.74E-05 0.15E-06 0.20E-08
51000 0.18E-04 0.38E-06 0.50E-08
51250 0.24E-04 0.49E-06 0.65E-08
51500 0.30E-04 0.62E-06 0.82E-08
51750 0.22E-04 0.44E-06 0.59E-08
52000 0.17E-04 0.35E-06 0.46E-08
52250 0.13E-04 0.27E-06 0.35E-08
52500 0.86E-05 0.18E-06 0.23E-08
52750 0.80E-05 0.17E-06 0.22E-08
53000 0.83E-05 0.17E-06 0.23E-08
53250 0.97E-05 0.20=-06 0.26E-08
53500 0.13E-04 0.26E-06 0.35E-08
53750 0.18E-04 0.38E-06 0.50E-08
54000 0.15E-04 0.30E-06 0.40E-08
54250 0.94E-05 0.19E-06 0.26E-08
54500 0.94E-05 0.19E-06 0.26E-08
54750 0.97E-05 0.20E-06 0.26E-08
55000 0.87E-05 0.18E-06 0.24E-08
55250 0.63E-05 0.13E-06 0.17E-08
55500 0.68E-05 0.14E-06 0.18E-08
55750 0.81E-05 0.17E-06 0.22E-08
56000 0.50E-05 0.10E-06 0.14E-08

TABLE IV

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 6000°K

⊽ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <sub>o</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>ο</sub> = 10-6
1250 1500 1750 2000 2250 2500 2750 3000 3250 3500 3750 4000 4250 4500 4750 5000 5250 5500 5750 6000 6250 6500	0. 0. 0.15E-07 0.28E-07 0.14E-07 0. 0. 0. 0. 0. 0.14E-07 0.37E-07 0.37E-07 0.16E-07 0.48E-07 0.95E-07 0.17E-06 0.18E-06 0.29E-06 0.57E-06 0.12E-05 0.12E-05 0.12E-05 0.18E-05	ρ/ρ = 10-5  0.  0.  0.16E-09  0.30E-09  0.15E-09  0.  0.  0.  0.16E-09  0.42E-09  0.42E-09  0.18E-09  0.11E-08  0.20E-08  0.22E-08  0.34E-08  0.69E-08  0.14E-07  0.11E-07  0.15E-07  0.22E-07;	0. 0. 0.16E-11 0.30E-11 0.15E-11 0. 0. 0.16E-11 0.42E-11 0.42E-11 0.18E-11 0.58E-11 0.12E-10 0.20E-10 0.20E-10 0.35E-10 0.70E-10 0.14E-09 0.12E-09 0.15E-09 0.22E-09
5750 6000 6250	0.12E-05 0.95E-06 0.12E-05 0.12E-05	0.11E-07 0.14E-07 0.15E-07	0.12E-09 0.15E-09 0.15E-09

TABLE IV (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 6000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	$\rho/\rho_{0} = 10^{-5}$	ρ/ρ <sub>o</sub> = 10-6
12250	_0.19E-04	U.23E-06	0.23E-08
12500	0.176-04	0.20E-06	0.20E-08
12750	0.14E-04	0.17E-06	0.17E-08
13000	0.24E-04	0.29E-06	0.29E-08"
13250	0.52E-04	0.63E-06	0.64E-03
13500	0.48E-04	0.57E-06	0.58E-08
13750	0.36E-04	0.43E-06	0.44E-08
14000	0.24E-04	0.29E-06	0.29E-08
14250	0.15E-04	0.18E-06	0.18E-08
14500	0.95E-05	0.11E-06	0.12E-08
14750	0.17E-04	0.20E-06	0.20E-08
15000	0.246-04	0.29E-06	0.29E-08
15250	0.29E-04	0.34E-06	0.35E-08
15500	0.36E-04	0.43E-06	0.44E-08
15750	0.22E-04	0.27E-06	0.27E-08
16000	0.21E-04	0.26E-06	0.26E-08
16250	0.14E-04	0.17E-06	0.17E-08
16500	0.135-04	0.16E-06	0.16E-08
16750	0.13E-04	0.16E-06	0.16E-08
17000	0.18E-04	0.22E-06	0.22E-08
17250	0.18E-04	0.226-06	0.22E-08
17500	0.15E-04	0.18E-06	0.18E-08
17750	0.64E-05	0.77E-07	0.79E-09
18000	0.24E-05	0.29E-07	0.29E-09
18250	0.295-05	0.34E-07	0.35E-09
18500	0.40L-05	0.49E-07	0.49E-09
,18750	0.50E-05	0.60E-07	0.61E-09 0.63E-08
19000	0.58E-05	0.21E-06	0.63E-08
19250 19500	0.79E-05	0.24E+06	0.12E-07
19750	0.986-05	0.38E-06	0.12E-07 0.57E-08
20000	0.50E-05 0.50E-05	0.18E-06 0.18E-06	0.57E-08
20250	0.50E-05	0.18E-06	0.57E-08
20500	0.52E-05	0.19E-06	0.60E-08
. 20750	0.52E-05	0.19E-06	0.60E-08
21000	0.52E-05	0.19E-06	0.60E-08
21250	0.386-04	0.15E-05	0.49E-07
21500	0.38E-04	0.15E-05	0.49E-07
21750	0.38E-04	0.15E-05	0.49E-07
22000	0.24E-04	0.97E-06	0.31E-07
22250	0.88E-05	0.34E-06	0.11E-07
22500	0.88E-05	0.34E-06	0.11E-07
22750	0.64E-05	· 0.23E-06	0.72E-08
23000	0.61E-05	0.23E-06	0.71E-08
23000	1 30010 07	92232 90	

TABLE IV (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 6000°K

<b>⊽</b> (cm <sup>-1</sup> )	$\rho/\rho_o = 10^{-4}$	ρ/ρ = 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
23250	0.27E-05	0.68E-07	0.18E-08
23500	0.32E-03	0.13E-04	0.42E-06
23750	0.32E-03	0.13E-04	0.42E-06
24000.	0.11E-03	0.44E-05	0.14E-06
24250	0.62E-04 0.23E-04	0.25E-05	0.81E-07
24500	0.23E-04 0.10E-04	0.89E-06	0.28E-07 0.10E-07
24750 25000	0.73E-05	0.33E-06 0.21E-06	0.62E-08
<u>25250</u>	0.15E-04	0.55E-06	0.02E-08
25500	0.56E-04	0.22E-05	0.71E-07
25750	0.12E-02	0.48E-04	0.16E-05
26000	0.80E-03	0.33E-04	0.11E-05
26250	0.39E-03	0.16E-04	0.51E-06
26500	0.16E-03	0.66E-05	0.21E-06
26750	0.79E-04	0.30E-05	0.97E-07
27000	0.38E-04	0.13E-05	0.42E-07
27250	0.23E-04	0.74E-06	0-22E-07
27500	0.12E-04	0.28E-06	0.73E-08
27750 28000	0.11E-04 0.63E-03	0.24E-06 0.25E-04	0.61E-08 0.82E-06
28250	0.03E-03	0.29E-04	0.02E-05
28500	0.47E-03	0.19E-04	0.61E-06
28750	0.23E-03	0.93E-05	0.30E-06
29000	7 0.12E-03	0.45E-05	0.14E-06
29250	0.67E-04	0.25E-05	0.79E-07
<u> 29500</u>	0.36E-04	0.12E-05	0.38E-07
29750	0.30E-04	0.67E-06	0.16E-07
30000	0.17E-04	0.30E-06	0.60E-08
30250	0.75E-04 0.25E-03	0.27E-05 0.97E-05	0-86E-07
30500	0.23E-03	0.97E-05	0.31E-06 0.16E-06
30750. 31000	0.13E 03	0.28E-05	0.10E-03 0.87E-07
31250	0.41E-04	0.14E-05	0.43E-07
31500	0.24E-04	0.78E-06	0.23E-07
31750.	0.26E-04	0.53E-06	0.12E-07
32000	0.23E-04	0.36E-06	0.65E-08
32250	0-20E-04	0-29E-06	0.49E-08
32500	0.26E-04	0.60E-06	0.16E-07
32750	0-23E-04	0.50E-06	0.12E-07
3,3000	0.15E-04	0.30E-06	0.72E-08
33250	0.14E-04	0.22E-06	0.45E-08
33500	0.15E-04	0.16E-06	0.16E-08
33750	0.16E-04 0.24E-04	0.17E-06 0.27E-06	0.17E-08 0.27E-08
34000	U. Z4E-04	U.2/E-U0	V+4/E-00

TABLE IV (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 6000°K

the same of the sa	الكنيبيان والمستنفض وربين والأناب ويسرونها	<del></del>	
ິ⊽ (cm <sup>-1</sup> )	p/p <sub>o</sub> = 10 <sup>-4</sup>	ρ/ρ <sub>σ</sub> = 10 <sup>-5</sup>	p/p # 10*6
34250	· 0.22E-04	0.24E-06	0.24E-08
34500	0.23E-04	0.25E-06	0.25E-08
34750	0.21E-04	0.23E-06	0.23E-08
35000	0.25E-04	0.27E-06	0.27E-08
35250	0.28E-04	0.30E-06	0.30E-08
35500	0.28E-04	0.30E-06	0.30E-08
35750	0.31E-04	0.34E-06	0.34E-08
36000	0.28E-04	0.30E-06	0.30E-08
•	0.29E-04	0.30E-06	0.31E-08
36250 36500	0.27E-04	0.29E-06	0.29E-08
	0.28E-04	0.27E 00 0.31E-06	0.31E-08
<u>36750</u>	0.41E-04	0.44E-06	0.44E-08
37000.	0.41E-04	0.44E-06 0.36E-06	0.36E-08
37250	0.41E-04	0.44E-06	0.36E-08
37500	0.34E-04		0.44E-08 0.37E-08
37750	0.34E-04	0.37E-06	
38000	0.30E-04	0.36E-06	0-36E-08
38250	0.30E-04 0.28E-04	0.33E-06	0.33E-08
38500		0-30E-06	0.30E-08
<u>38750</u>	0.56E-04 0.46E-04	0.60E-06	0.60E-08
39000		0.50E-06	0.50E-08
39250	0.47E-04	0.51E-06	0.51E-08
39500	0.41E-04	0-44E-06	0.44E-08
39750	0.33E-04	0.35E-06	0.35E-08
40000	0.30E-04	0.32E-06	0.32E-08
40250	0.23E-04	0.25E-06	0.25E-08
40500	0.62E-04	0.68E-06	0.68E-08
40750	0.49E-04	0.53E-06	0.53E-08
41000	0.47E-04	0.51E-06	.0.51E-08
41250	0.33E-04	0.35E-06	0.35E-08
41500	0.28E-04	0.30E-06	0.30E-08
<u>41750</u>	0.27E-04	0.29E-06	0.29E-08
42000	0.20E-04	0.22E-06	0.22E-08
42250	0.58E-04	0.63E-06	0∙63E~08 .
42500	0.75E-04	0.81E-06	0.81E-08
<u>42750</u>	0.59E-04	0.64E-06	0.64E-08
43000	0.41E-04	0.44E-06	0-44E-08
43250	0.37E-04	0.40E-06	0-40E-08
43500	0.30E-04	0.32E-06	0.32E-08
<u>43750</u>	0.46E-04	0.50E-06	0.50E-08
44000	0.22E-04	0.24E-06	0.24E-08
44250	0.94E-04	0.10E-05	0.10E-07
44500	0.72E-04	0.78E-06	0.78E-08
. 44750	0.75E-04	0.81E-06	0.81E-08
45000	0.64E-04 .	0.69E-06	0.69E-08
		ليك وتنصيب	

TABLE IV (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 6000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <sub>e</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
<u>45250</u>	0.58E-04	0.63E-06	0.63E-08
45500	0.50E-04	0.54E-06	0.54E-08
45750	0.37E-04	0.41E-06	0.41E-08
46000	0.33E-04	0.36E-06	0.36E-08
46250	0.30E-04	0.33E-06	0.33E-08
46500	0.39E-04	0.42E-06	0.42E-08
46750	0.90E-04	0.98E-06	0.98E-08
<u>47000</u> 47250	0.66E-04	0.71E-06	0.71E-08
· <del>-</del>	0.51E-04 0.48E-04	0.56E-06	0.56E-08
<u>47500</u> 47750	0.48E-04	0.52E-06 0.37E-06	0.52E-08
2	0.30E-04	0.37E-06	0.37E-08 0.32E-08
<u>48000</u> 48250	0.34E-04	0.37E-06	0.32E-08
, 48500 ·	0.26E-04	0.37E-06	0.37E-08
48750	0.32E-04	0.26E-06	0.25E-08
49000	0.81E-04	0.33E-06	0.39E-08
49250	0.87E-04	0.00E 00	0.88E-08
49500	0469E-04	0.74E-06	0.74E-08
49750	0-53E-04	0.71E 00	0.14E 00
50000	0.47E-04	0.51E-06	0.51E-08
50250	0.40E-04	0.43E-06	0.43E-08
50500	0.22E-04	0.24E-06	0.24E-08
50750	0.20E-04	0.22E-06	0.22E-08
51000	0.31E-04	0.33E-06	0.33E-08
51250	0.48E-04	0.52E-06	· 0.52E-08
51500.	0.65E-04	0.70E-06	0.70E-08
51750	0.47E-04	0.51E-06	0.51E-08
52000	0.39E-04	0.42E-06	0.42E-08
52250.	0.31E-04	0.34E-06	0.34E-08
52500	0.24E-04	0.26E-06	0.26E-08
52750.	* 0.22E-04	0.23E-06	. 0.23E-08
53000	0.21E-04	0.23E-06	0.23E-08
53250	0.23E-04	0.25E-06	0.25E-08
<u>53500</u> .	0.30E-04	0.32E-06	0.32E-08
53750.	0.42E-04.	0.46E-06	0.46E-08
54000	0.37E-04	0.41E-06	0.41E-08
54250	0.27E-04	0.29E-06	0.29E-08
<u>54500</u>	0.25E-04	0.27E-06	0.27E-08
54750	0.30E-04	0.32E-06	0.32E-08
55000	0.22E-04	0.24E-06	0.24E-08
55250	· 0 • 17E-04	0.18E-06	0-18E-08
<u>55500</u>	0.20E-04	0.22E-06	0.22E-08
55750	0.20E-04	0.22E-06	0.22E-08
56000	0.13E-04	0.15E-06	0.15E-08

TABLE V

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 7000°K

⊽ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ <sub>e</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
1250	0.20E-06	<pre>/0.20E-07 0.22E-07</pre>	0.19E-08 0.21E-08
1500 1750	0.22E-06 10.23E-06	0.22E-07	0.21E-08
2000	0.27E-06	0.27E-07	0.26E-08
2250	0.29E-06	0.29E-07	0.27E-08
2500	0.30E-06	0.30E-07	0.28E-08
2750	0.31E-06	0.31E-07	0.29E-08
3000	0.33E-06	0.33E-07	0.31E-08
3250	0.38E-06	0.37E-07	0.36E-08
3500	0.41E-06	0.40E-07	0.39E-08
3750	0.78E-06	0.78E-07	0.74E-08,
4000	0.75E-06	0.73E-07 0.74E-07	0.70E-08 0.70E-08
<u>4250</u> 4500	0.76E-06 0.84E-06	0.79E-07	0.76E-08
4750	0.84E-08	0.83E-07	0.78E-08
5000	0.73E-06	0.64E-07	0.61E-08
5250	0.92E-06	0.77E-07	· 0.72E-08
5500	0.12E-05	0.89E-07	0.82E-08
5750	0.17E-05	0.11E-06	0.98E-08
6000	0.18E-05	, 0.12E-06	0.11E-07
6250	0.14E-05	0.75E-07	0.65E-08
6500	0.15E-05	0.84E-07	0.73E-08
6750	0.10E-05	0.10E-07	0.93E-10
7000	0.20E-05 0.23E-05	0.20E-07 0.22E-07	0.19E-09 0.21E-09
<u>7250</u> 7500	0.23E-05	0.22E-07	0.21E-09
7750	0.21E-05	0.21E-07	0.20E-09
8000	0.15E-05	0.15E-07	0.13E-09
8250	0.68E-05	0.67E-07	0.62E-09
8500	0.73E-05	0.73E-07	0.67E-09
8750	0.63E-05	0.63E-07	0.58E-09
9000	0.50E-05	0-49E-07	0.45E-09
9250	0.45E-05	0.45E-07	0.41E-09
9500	0.45E-05	0.45E-07	0.41E-09
9750	0.11E-04	0.11E-06 0.11E-06	0.10E-08 0.10E-08
10000 10250	0.11E-04 0.11E-04	0.11E-06	0.10E-08
10250	0.11E-04	0.11E-06	0.10E-08
10750	0.11E-04	0.10E-06	0.10E 00
11000	0.84E-05	0.83E-07	0.76E-09
11250	0.93E-05	0.92E-07	0.84E-09
11500	0.29E-04	0.29E-06	0.27E-08
11750	0.23E-04	0.23E-06	0.22E-08
12000	0.18E-04	0-21E-06	0.27E-08

TABLE V (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 7000°K

♥ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	p/p <sub>o</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
12250	0.14E-04	"0.16E-06	0.23E-08
12500	0.13E-04	0.15E-06	0.22E-08
12750	0.13E-04	0.166-06	0.23E-08
13000	0.21E-04	0.24E-06	0.31E-08
13250	0.37E-04	0.43E-06	0.59E-08
13500	0.36E-04	0.42E-06	0.58E-08
13750	0.28F-04	0.34E-06	0.51E-08
14000	0.21E-04	0.27E-06 ·	0 • 44E - 08
14250	0.15E-04	0.22E-06	0.41E-08
14500	0.12E-64	0.18E-06	0.38E-08
14750	0.156-04	0.22E-06	0.44E-08
15000	0.26E-04	0.34E-06	0.54E-08
15250	0.26E-04	0.34E-06	0.54E-08
15500	0.29E-04	0.37E-06	0.59E-08
15750	0.24E-04	0.32E-06	0.55E-08
16000	0.266-04	0.35E-06 `	0.59E-08
16250	0.16E-04	0.26E-06	0.5%E-08
16500	0.16E-04	0.27E-06	0.57E-08
16750	0.16E-04	0.27E-06	0.60F-08
17000	0.30E-04	0.42E-06	0.735-08
17250	0.31E-04	0.43E-06	0.74E-08
17500	0.17E-04	0.28E-06	0.61E-08
17750	0.12E-04	0.24E-06	0.59E-08
18000	0.88E-05	0.21E-06	0.56E-08
18250	0.87E-05	0-22E-06	0.58E-08
18500	0.95E-05	0.226-06	0.59E-08
18750	0.98E-05	0.23E-06	0.59E-08
19000	0.19E-04	0.57E-06	0.17E-07
19250	0.20E-04	0.61E-06	0.18E-07
19500	0.28E-04	0.85E-06	0.25E-07
19750	. 0.12E-04	0-32E-06	0.92E-08
20000	0.13E-04	0.40E-06	0.12E-07
20250	0.98E-05	0.31E-06	0.91E-08
20500	0.98E-05	0.31E-06	0.91E-08
20750	0.98E-05	0.31E-06	0.91E-08
21000	0.98E-05	0.31E-06	0.91E-08
21250	0.73E-04	0.23E-05	0.68E-07
21500	0.87E-04	0.28E-05	0.82E-07
21750	0.15E-03	0.48E-05	0.14E-06
22000	0.15E-03	0.49E-05	0.14E-06
22250	0.37E-04	0.11E-05	0.33E-07
22500	0.17E-04	0.52E-06	0.15E-07
22750	0.12E-04	0.34E-06	0.98E-08
23000	0.13E-04	0.39E-06	0.11E-07

TABLE V (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 7000°K

⊽ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ <sub>o</sub> = 10 <sup>-5</sup>	p/p <sub>0</sub> = 10-6
23250	0.12E-04	0.34E-06	0.95E-08
23500	0.74E-03	0.23E-04	0.70E-06
23750	0.74E-03	0.23E-04	0.70E-06
24000	0.38E-03	0.12E-04	0.35E-06
24250	0.20E-03	0.61E-05	0.18E-06
24500	0.85É-04	0.26E-05	0.78E-07
24750	0.45E-04	0.14E-05	0.40E-07
25000	0.27E-04	0.80E-06	0.23E-07
25250	0.20E-04	0.52E-06	0.14E-07
25500	0.21E-03	0.65E-05	0.19E-06
25750	0.27E-02	0.85E-04	0.25E-05
26000	0.17E-02	0.53E-04	0.16E-05
26250	0.90E-03	0.28E-04	0.84E-06
26500	0.42E-03	0.13E-04	0.39E-06
26750	0.25E-03	0.77E-05	0.23E-06
27000	0.14E-03	0.43E-05	0.13E-06
27250	0.76E-04	0.22E-05	0.64E-07
27500	0.45E-04	0.13E-05	0.37E-07
27750	0.30E-04	0.81E-06	0.23E-07
28000	0.28E-03	0.85E-05	0.25E-06
28250	0.23E-02	0.73E-04.	0.22E-05
28500	0.11E-02	0.35E-04	0.10E-05
28750	0.72E-03	0.22E-04	0.67E-06
29000	0.39E-03	0.12E-04	0.36E-06
29250	0.24E-03	0.73E-05	0.22E-06
29500	0.13E-03	0.41E-05	0.12E-06
29750	0.10E-03	0.27E-05	0.76E-07
30000	0.61E-04	0.15E-05	0.42E-07
30250	: 0-51E-04	0.13E-05	0.36E-07
30500	0.686-03	0.21E-04	0.63E-06
30750	0.36E-03	0.11E-04	0.33E-06
31000	0.23E-03	0.71E-05	0.21E-06
31250	0.13E-03	0.39E-05	0.12E-06
31500	0.80E-04	0-24E-05	0.70E-07
31750	0.65E-04	0.16E-05	0.42E-07
32000	0.52E-04	0.12E-05	0.30E-07
32250	0.40E-04	0.79E-06	0.19E-07
32500	0.45E-04	0.10E-05	0.27E-07
32750	0.47E-04	0.12E-05	0.31E-07
33000	0.33E-04	0.79E-06	0.21E-07
33250	0.24E-04	0.55E-06	0.15E-07
33500	0.208-04	0.43E-06	0.11E-07
33750	0.22E-04	0.36E-06	0.75E-08
34000	0.30E-04	0.44E-06	0.83E-08

TABLE V (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 7000°K

ິນ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ <sub>e</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>σ</sub> # 10-6
34250	0-29E-04	0.43E-06	0.82E-08
34500	0.27E-04	0.416-06	0.80E-08
34750	0.25E-04	0.39E-06	0.78E-08
35000	0.27E-04	0.40E-06	0.78E-08
35250	0.29E-04	0.41E-06	0.76E-08
35500	0.28E-04	0.401-06	0.76E-08
35750	0.33E-04	0.45E-06	0.80E-08
36000	0.28E-04	0.41E-06	0.76E-08
36250	0.30E-04	0.42E-06	0.77E-08
36500	0.27E-04	0.39E-06	0.72E-08
36750	0.33E-04	0.45E-06	0.78E-08
37000	0.38E-04	0.50E-06	0.82E-08
37250	0.32E-04	0.44E-06	0.77E-08
37500	0.38E-04	0.491-06	0.82E-08
<u>37750</u>	0-34E-04	0.45E-06 0.45E-06	0.76E-08
38000	0.34E-04		0.76E-08
38250	0-32E-04	0.43E-06	0.74E-08
38500	0.31E-04	0.415-06	0.71E=08
38750	0.49E-04 0.42E-04	0.59E-06 0.52E-06	0.87E-08 0.81E-08
39000		0.54E-06	0.81E-08
39250	0.44E-04; 0.38E-04	0.54E-06	0.75E-08
39500.	0.36E-04	0.45E-06	0.73E-08
<u>39750</u> 40000	0.31E-04	0.41E-06	0.69E-08
40250	0.25E-04	0.34E-06	0.60E-08
<u>40250</u> 40500	0.49E-04	0.58E-06	0.82E-08
40750	0.44E-04	0.53E-06	0.78E-08
41000	0.42E-04	0.51E-06	0.74E-08
41250	0.35E-04	0.43E-06	0.65E-08
41500 ·	0.28E-04	0.36E-06	0.58E-08
41750	0.16E-04	0.24E-06	0.45E-08
42000	0.22E-04	0.29E-06	0.50E-08
42250	0.46E-04	0.53E-06	0.72E-08
42500	0.59E-04	0.66E-06	0.84E-08
42750	0.48E-04	0.55E-06	0.74E-08
43000	0.37E-04	043E-06	0.61E-08
43250	0.34E-04	0.41E-06	0.59E-08
43500	0.32E-04	0.39E-06	0.57E-08
43750	D.30E-04	0.36E-06	0.55E-08
44000	0.22E-04	0.28E-06	0.45E-08
44250	0.72E-04	0.77E-06	0.90E-08
44500	0.58E-04	0.64E-06	0.78E-08
44750	0.64E-04	0.70E-06	0.83E-08
45000	0.55E-04	0.60E-06	0.73E-08

TABLE V (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 7000°K

⊽ (cm <sup>-1</sup> )	$\rho/\rho_o = 10^{-4}$	ρ/ρ <sub>σ</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
45250	0.555-04	0.60E-06	0.73E-08
45500	0.476-04	0.52£-06	0.66E-08
45750	0.44E-04	0.49E-06	0.62E-08
46000	0.33E-04	0.38E-06	0.52E-08
46250	0.336-04	0.438E-06	0.51E-08
4650.0	0.456-04	0.496-06	0.61E-08
46750	0.736-04	0.77E-06	0.87E-08
47000	Q.62E-04	0.66E-06	0.76Ë−08
47250	0.536-04	0.57E-06	0.67E-08
47500	0.49E-04	0.53E-06	0.62E-08
47750	0.38E-04	0.42E-06	0.53E-08
48000	0.33E-04	0.37E-06	0.47E-08
48250	0.318-04	0.35E-06	0.46E-08
48500	0.27E-04	0.31E-06	0.42E-08
48750	0.435-04	0.47E-06	0.56E-08
4,9000	0.70E-04	0.72E-06 `	0.79E-08
49250	0.786-04	0.81E-06	0.86E-08
49500	0.64E-04 c	0.67E-06	0.73E-08 '
49750	0.53E-04	0.56E-06	0.63E-08
50000	- 0.44E-04	0.47E-06	0.54E-08
50250	C.40E-04	. 0.43≿-06	0.50E-08
50500	0.256-04	0.28E-06	0.36E-08
50750	0.226-04	0.25E-06	0.33E-08
51000	0.38E-04	0.40E-06	0.47E-08
51250	0.46E-04	0.48E-06	0.54E-08
51500	0.66E-04	0.68E-06	0.72E-08
51750	0.51E-04	0.53E-06	0.59E-08
52000	0.43E-04	0.45E-06	0.50E-08
52250	0.35E-04	0.37E-06	0.43E-08
52500	0.29E-04	0.31E-06	0.37E-08
52750	0.28E-04	0.30E-06	0.36E-08
53000	0.25E-04	0.27E-06	0.33E-08
53250	0.296-04	0.31E-06	0.36E-08
53500	0.33E-04	0.35E-06	0.40E-08
53750	0.456-04	0.46E-06	0.50E-08
54000	0.37E-04	0.39E-06	0.43E-08
54250	0.39E-04	0.40E-06	0.44E-08
54500	0.27E-04	0.285-06	0.32E-08
54750	0.26E-04	0.27E-06	0.32E-08
55000	0.21E-04	0.23E-06	0.27E-08
. 55250	0.17E-04	0.18E-06	0.23E-08
55500	0.19E-04	0.21E-06	0.25E-08
55750	0.20E-04	0.22E-06	0.26E-08
56000	0.14E-04	0.15E-06	0.20E-08

TABLE VI

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 8000°K

೪ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <sub>o</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
1250	0.11E-05	0.10E-06	0.86E÷08
1250 1500	0.12E-05	0.11E-06	0.94E-08
1750	0.13E-05	0-12E-06	0.10E-07
2000	0.15E-05	0-14E-06	0.12E-07
2250	0.18E-05	0.17E-06	0.14E-07
2500	0.19E-05	0.18E-06	0.15E-07
2750	0.19E-05	0.18E-06	0.15E-07
3000	0.20E-05	0.19E-06	0.16E-07
3250	0.30E-05	0.27E-06	0.23E-07
3500	0.39E-05	0.35E-06	0.31E-07
3750	0.44E-05	0-39E-06	0.34E-07
4000	0.46E-05	0.41E-06	0.36E-07
4250	0.50E-05 0.52E-05	0.45E-06	0.39E-07
4500	,	0.46E-06	0.41E-07
4750	0.56E-05 0.59E-05	0.49E-06 0.52E-06	0.43E-07 0.45E-07
5000	0.63E-05	0.52E-06	0.45E-07
<u>5250</u>	0.63E-05	0.53E-06	0.47E-07
5500 5750	0/. 72E-05	0.53E-06 0.61E-06	0.47E-07
5750	0.72E-05	0.61E-06	0.54E-07
6000	0.75E-05	· 0.63E-06	0.55E-07
<u>6250</u> 6500	0.85E-05	0.72E-06	0.63E-07
6750	0.76E-05	0.63E-06	0.54E-07
7000	0.90E-05	0.74E-06	0.64E-07
7250	0.10E-04	0.82E-06	0.70E-07
7500	1.00E-05	0.80E-06	0.69E-07
7750	0.11E-04	0.89E-06	0.77E-07
8000	0.98E-05	0.81E-06	0.69E-07
8250	0.13E-04	0.89E-06	0.76E-07
8500	0.13E-04	0.88E-06	0.74E-07
8750	0.13E-04	0.93E-06	0.79E-07
9000	0.14E-04	0.10E-05	0.86E-07
9250	· 0.14E-04	0.10E-05	0. 86E-07
9500	0.15E-04	0.11E-05	0.92E-07
9750	0.21E-04	0.12E-05	0.10E-06
10000	0.17E-04	0.94E-06	0.79E-07
_10250	0.18E-04	0.10E-05	0.85E-07
10500	0.15E-04	0.76E-06	0.62E-07
<u>. 10750</u>	0.15E-04	0.81E-06	0.66E-07
: 11000	0.14E-04	0.84E-06	0.69E-07
<u>11250</u>	0.16E-04	0.91E-06	0.75E-07
11500	0.25E-04	0.10E-05	0.78E-07
<u>. 11750</u> .	0.26E-04	0.12E-05	0.86E-07
12000	0.27E-04	0.13E-05	0.93E-07

TABLE VI (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 8000°K

	t (Watts) CIII - St	·	1 = 0000 K
♥ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <sub>0</sub> = 10 <sup>-5</sup>	p/p = 10-6
12250 12500 12750 13000 13250 13500 13750 14000	0.27E-04 0.31E-04 0.31E-04 0.33E-04 0.47E-04 0.49E-04 0.48E-04 0.43E-04	0.13E-05 0.15E-05 0.15E-05 0.16E-05 0.18E-05 0.19E-05 0.20E-05 0.20E-05	0.98E-07 0.11E-06 0.11E-06 0.11E-06 0.12E-06 0.13E-06 0.13E-06 0.14E-06
14250 14500 14750 15000 15250 15500 15750 16000	0.36E-04 0.25E-04 0.28E-04 0.33E-04 0.35E-04 0.35E-04 0.35E-04	0.14E-05 0.61E-06 0.65E-06 0.71E-06 0.74E-06 0.80E-06 0.78E-06	0.80E-07 0.14E-07 0.14E-07 0.15E-07 0.16E-07 0.17E-07 0.17E-07
16250 16500 16750 17000 17250 17500	0.38E-04 0.38E-04 0.38E-04 0.40E-04 0.47E-04 0.44E-04 0.40E-04	0.90E-06 0.93E-06 0.94E-06 0.98E-06 0.11E-05 0.11E-05 0.10E-05	0.18E-07 0.20E-07 0.21E-07 0.22E-07 0.22E-07 0.24E-07 0.24E-07
18000 18250 18500 18750 19000 19250 19500	0.37E-04 0.39E-04 0.38E-04 0.40E-04 0.70E-04 0.52E-04 0.65E-04	0.10E-05 0.11E-05 0.11E-05 0.11E-05 0.20E-05 0.15E-05 0.19E-05	0.24E-07 0.24E-07 0.26E-07 0.26E-07 0.46E-07 0.36E-07 0.44E-07
19750 20000: 20250 20500 20750 21000 21250	0.46E-04 0.42E-04 0.43E-04 0.43E-04 0.43E-04 0.19E-03	0.13E-05 0.12E-05 0.12E-05 0.12E-05 0.12E-05 0.12E-05 0.54E-05	0.32E-07 0.32E-07 0.29E-07 0.30E-07 0.30E-07 0.30E-07 0.30E-07
21500 21750 22000 22250 22500 22750 23000	0.17E-03 0.23E-03 0.17E-03 0.11E-03 0.66E-04 0.53E-04	0.48E-05 0.66E-05 0.48E-05 0.31E-05 0.19E-05 0.15E-05 0.16E-05	0.11E-06 0.15E-06 0.11E-06 0.73E-07 0.46E-07 0.37E-07

TABLE VI (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 8000°K

ν̃ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	$\rho/\rho_{0} = 10^{-5}$	ρ/ρ <sub>o</sub> = 10 <sup>-6</sup>
23250	0.62E-04	0.18E-05	0.43E-07
23500	0.11E-02	0.31E-04	0.71E-06
23750	0.12E-02	0.35E-04	0.80E-06
· <u>24000</u>	0.68E-03	0.20E-04	0.45E-06
24250	0.37E-03	0.11E-04	0.24E-06
24500	0.21E-03	0.61E-05	0.14E-06
24750	0.14E-03	0.39E-05	0.92E-07
25000	0.92E-04	0.26E-05	0.61E-07
25250	0.73E-04	0.21E-05	0.49E-07
<u>25500</u>	0.25E-03	0.70E-05	0.16E-06
25750	0.35E-02	0.10E-03 0.75E-04	0.23E-05 0.17E-05
26000	0.26E-02		0.17E-05
26250 26500	0.16E-02 0.87E-03	0.46E-04 0.25E-04	0.57E-06
26750	0.57E-03	0.15E-04	0.35E-06
27000	0.31E-03	0.88E-05	0.20E-06
27250	0.20E-03	0.57E-05	0.13E-06
27500	0.15E-03	0.41E-05	0.94E-07
27750	· 0.97E-04	0.27E-05	0.64E-07
28000	0.19E-02	0.56E-04	0.13E-05
28250	0.32E-02	0.91E-04	0.21E-05
28500	0.20E-02	0.57E-04	0.13E-05
28750	0.13E-02	0.38E-04	0.86E-06
_29000	0.85E-03	0.24E-04	0.55E-06
29250	0.44E-03	0.12E-04	0.29E-06
29500	0.31E-03	0.88E-05	0.20E-06
29750	0.23E-03	0.63E-05	0.14E-06
30000	0-16E-03	0.43E-05	0.99E-07
30250.	0.34E-03	0.78E-05	0.17E-06
30500	0.11E-02	0.29E-04	0.66E-06
30750.	0.69E-03	0.20E-04	0.45E-06
31000	0.38E-03	0.11E-04	0.24E-06
31250	0.31E-03	0.88E-05	0.20E-06
31500	0.21E-03	0.60E-05	0.14E-06
31750	0.17E-03	0.44E-05	0.99E-07
32000 32250	0.13E-03 0.11E-03	0.35E-05	0.79E-07 0.60E-07
32500	0.11E-03 0.98E-04	0.27E-05 0.25E-05	0.56E-07
32750	0.98E-04 0.12E-03	0.25E-05 0.31E-05	0.70E-07
33000	0.12E-03	0.26E-05	0.60E-07
33250	0.78E-04	0.20E-05	0.49E-07
33500	0.70E-04	0.21E-05	0.44E-07
33750	0.10E-04 0.69E-04	0.18E-05	0.41E-07
34000	0.09E-04	0.19E-05	0.42E-07
, 34000	0 4 7 C - 0 <del>4</del>	0.17. 07	

TABLE VI (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 8000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <b>= 10<sup>-5</sup></b>	p/p <sub>o</sub> = 10-6
34250	0.70E-04	0.176-05	0.38E-07
34500	0.68E-04	0.17E-05	0.38E-07
34750	0-63E-04	04150-05	0.35E-07
35000	0.63E-04	0.15E-05)	0.35E-07
35250	· 0.66E-04	0.16E-05	0.35E-07
35500	0.62E-04	0.15E-05	0.336-07
35750	0.64E-04	0.15E-05	0.33E-07
36000	0.62E-04	0.15E-05	0.33E-07
36250	0.62E-04	0.15E-05	0.33E-07
36500	0.62E-04	0.15E-05	0.33E-07
36750	0.63E-04	0.15E-05	0.33E-07
37000	0-64E-04	0.15E-05	0.33E-07
37250	0.61E-04	0.14E-05	0.31E-07 0.31E-07
37500	0.65E-04	0.14E-05	
37750	0.59L-04	0.13E-05	0.29E-07 0.29E-07
38000	0.59E-04	0.13E-05	0.29E-07
38250	0.59E-04	0.13E-05 0.13E-05	0.29E-07
38500	0.58E-04	0.13E-05	0.27E-07
38750	0.65E-04	0.13E-05	0.27E-07
39000	0.63E-04	0.13E-05	0.27E-07
39250	0.64E-04	0.13E-05	0.27E-07
39500	0.62E-04 0.56E-04	0.120-05	0.27E-07
39750	0.54E-04	0.12E-05	0.27E-07
40000	0.54E-04	0.12E-05	0.27E-07
40250	0.66E-04	0.13E-05	0.28E-07
40500 40750	0.65E-04	0.13E-05	0.27E-07
41000	0.65E-04	0.13E-05	0.28E-07
41250	0.54E-04	0.12E-05	0.25E-07
41500	0.52E-04	0.11E-05	0.25E-07
41750	0.48E-04	0.10E-05	0.23E-07 <sup>©</sup>
42000	0.44E-04	0.10E-05	0.22E-07
42250	0.57E-04	0.11E-05	0.23E-07
42500	0.67E-04	0.12E-05	0.24E-07
42750	0.61E-04	0.12E-05	0.23E-07
43000	0.55E-04	0.11E-05	0.23E-07
43250	0.54E-04	0.11E-05	0.23E-07
43500	0.50E-04	0.11E-05	0.23E-07
43750	0.48E-04	0.10E-05	0.22E-07
44000	0.43E-04	0.97L-06	0.21E-07
44250	0.76E-04	0.13E-05	0.23E-07
44500	0.70E=04	0-12E-05	0.22E-07
44750	0.73E-04	0.12E-05	0-22E-07 0-21E-07
45000	0.65E-04	0.T1E-05	0.215-01

TABLE VI (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 8000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ= 10 <sup>-5</sup>	ρ/ρ <sub>o</sub> = 10-6
45250	0.64E-04	0.11E-05	0.21E-07
45500	0.61E-04	0.11E-05	0.21E-07
45750	0.55E-04 ·	1.00E-06	0.20E-07
46000	0.49E-04	0.95E-06	0.19E-07
46250	0.50E-04	0.94E-06	0.19E-07
46500	0.66E-04	0.11E-05	0.20E-07
46750	0.77E-04	0.12E-05	0.20E-07
47000	0.67E-04	0.11E-05	0.19E-07
47250	0.63E-04	0.10E-05	0.19E-07
47500	0.59E-04	0.98E-06	0.18E-07
47750	0.53E-04	0.92E-06	0.17E-07
48000	0.50E-04	0.88E-06	0.17E-07
48250	0.48E-04	0.86E-06	0.17E-07
48500	0.44E-04	0.81E-06	0.16E-07
48750	0.43E-04	0.80E-06	0.16E-07
49000	0.76E-04	0.11E-05	0.18E-07
49250	0.78E-04	0.11E-05	0.18E-07
49500	0.73E-04	0.10E-05	0.17E-07
49750	0.86E-04	0.11E-05	0.17E-07
50000	0.57E-04	0.88E-06	0.15E-07
50250	0.51E-04	0.83E-06 L	0.15E-07
50500	0.40E-04	0.72E-06	0.14E-07
50750	0.38E-04	0.69E-06	0.14E-07
51000	0.41E-04	0.71E-06	0.14E-07
51250	0.54E-04	0.83E-06	0.14E-07
51500	0.70E-04	0.96E-06	0.15E-07
51750	0.61E-04	0.86E-06.	0.14E-07
52000	0.54E-04	0.80E-06	0.13E-07
52250	0.45E-04	0.71E-06	0.13E-07
52500	0.39E-04	0.65E-06	0.12E-07
52750	0.38E-04 ·	0.64E-06	0.12E-07
53000	0.37E-04	0.62E-06	0-11E-07
53250	0.38E-04	0.62E-06	0.11E-07
53500	0.42E-04	0.64E-06	0.11E-07
53750	0.49E-04	0.70E-06	0.11E-07
54000	0.43E-04	0.64E-06	0.11E-07
54250	0.40E-04	0.62E-06	0.11E-07
54500	0.37E-04	0.58E-06	0.10E-07
54750	0.36E-04	0.57E-06	0.10E-07
55000	0.33E-04	0.54E-06	0.98E-08
55250	0.30E-04	0.51E-06	0.97E-08
55500	0.30E-04	0.51E-06	0.95E-08
55750 ·	. 0.30E-04	0.50E-06	0.93E-08
56000	0.24E-04	0.45E-06	0.87E-08

TABLE VII

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 9000°K

ິ⊽ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ <b>= 10<sup>-5</sup></b>	ρ/ρ <b>± 10-6</b>
1250	0.56E-05	0 • 48E-06	0.32E-07
1500	0.59E-05	0.51E-06	0.34E-07
1750	0.61E-05	0.53E-06	0.35E-07·
2000	0.65E-05	0.56E-06	0.37E-07
2250	0.69E-05 0.71E-05	0-59E-06	0.39E-07
2500	0.75E=05	0.61E-06	0.41E-07 0.43E-07
<u>2750</u> 3000	0.75=05 0.80E-05	0.65E-06 0.69E-06	0.45E-07
3250	0.14E-04	0.13E-05	0.78E-07
3500	0.15E-04	0.14E-05	0.85E-07
3750	0.17E-04	0.15E-05	0.92E-07
4000	0.18E-04	0.16E-05	0.96E-0.7
4250	0.19E-04	0.17E-05	0.10E-06
4500	0.20E-04	0.18E-05	0.11E-06
4750	: 0.20E-04	0.18E-05	0.11E-06 !
5000	0.20E-04	0.18E-05	0.11E-06
5250	0.23E-04	0.21E-05	0.13E-06
5500	0.26E-04	0-23E-05	0.14E-06
5750	0.27E-04	0 • 24E-05	0.15E-06
6000	0.29E-04	0-26E-05	0.16E-06
6250	0.30E-04 0.32E-04	0 • 27E-05	0.16E-06
6500 6750	0.34E-04	0-28E-05 0-30E-05	0.17E-06 0.18E-06
7000	0.34E-04	0-30E-05	0.18E-06
7250	0.36E-04	0-32E-05	0.19E-06
$\frac{7500}{7500}$	0.40E-04	0.35E-05	0.21E-06
7750	0.39E-04	0.35E-05	0.21E-06
8000	0.39E-04	0.35E-05	0.21E-06
8250	0.42E-04	0.37E-05	0.22E-06
8500	0.46E-04	0.40E-05	0.24E-06
8750	0.46E-04	0-40E-05	0.24E-06
9000	0.49E-04	0.43E-05	0.26E-06
9250	0.48E-04	0.43E-05	0.26E-06
9500	0.53E-04	0.47E-05	0.28E-06
9750	0.52E-04	0-44E-05	0.26E-06
10000	0.55E-04	0:47E-05	0.28E-06
10250	0.57E-04 0.58E-04	0-49E-05	0.29E-06
10500 10750	0.58E-04 0.60E-04	0.50E-05 0.51E-05	0.30E-06 0.31E-06
11000	0.80E-04 0.57E-04	0.49E-05	0.31E-06
11250	0.61E-04	0.49E-05	0.31E-06
11500	0.68E-04	0.55E-05	0.33E-06
11750	0.77E-04	0.59E-05	0.35E-06
12000	0.76E-04	0.55E-05	0.31E-06

TABLE VII (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 9000°K

ν̃ (cm <sup>-1</sup> )	$\rho/\rho_{o} = 10^{-4}$	ρ/ρ <sub>o</sub> = 10 <sup>-5</sup>	p/p <sub>o</sub> = 10-6
12250	0.82E-04	0.58E-05	0.336-06
12500	0.876-04	0.605-05	0.34E-06
12750	0.93£-04	0.636-05	0.35E-06
13000	0.11E-03	0.71E-05	0.39E-06
13250	0.96E-04	0.60E-05	0.32E-06
13500	0.10E-03	0.610-05	0.33E-06
13750	0.116-03	0.64E-05	0.34E-06
14000	0.11E-03	0.67E-05	0.35E-06
14250	0.125-03	0.72E-05	0.38E-06
14500	0.11E-03	0.666-05	0.33E-06
14750	0.116-03	0.66E-05	0.33E-06
15000	0.11E-03	0.58E-05	0.28E-06
15250	0.12E-03	0.62E-05	0.30E-06
15500	0.12E-03	0.64E-05	0.31E-06
15750	0.13E-03	0.67E-05	0.32E-06
16000	0.13E-03	0.70E-05	0.34E-06
16250	0.11E-03	0.45E-05	0.17E-06
16500	011E-03	0.48E-05	0.18E-06
16750	0.11E-03	0.49E-05	0.19E-06
17000	0.12E-03	0.50L-05	0.19E-06 ·
17250	0.12E-03	0.53E-05	0.20E-06
17500	0.13E-03	0.55E-05	0.21E-06
17750	0.13E-03	0.58E-05	0.22E-06
18000	0.13E-03	. 0.59E-05	C.23E-06
18250	0.13E-03	0.520-05	0.19E-06 0.14E-06
18500	0.12E-03 ·	0.45E-05	0.14E-06
18750	0.12E-03	0.46E-05	0.14E-06
19000	0.14E-03 0.15E-03	0.63E-05 0.56E-05	0.16E-06
19250	0.15E-03	0.59E-05	0.10E 00 0.17E-06
19500	0.15E-03	0.566-05	0.16E-06
19750	0.15E-03	0.54E-05	0.16E-06
20000	0.12E-03	0.35E-05	0.62E-07
20250	0.12E-03	0.35E-05	0.62E-07
20500	0.126-03	0.35E-05	0.62E-07
20750 21000	0.13E-03	0.36E-05	0.65E-07
21000	0.13E-03	0.59E-05	0.93E-07
21500	0.25E-03	0.75E-05	0.11E-06
21750	0.29E-03	0.87E-05	0.13E-06
22000	0.28E-03	0.86E-05	0.13E-06
22250	0.22E-03	0.64E-05	0.10E-06
22500	0.18E-03	0.50E-05	0.85E-07
22750	0.17E-03	0.48E-05	0.83E-07
23000	0.160-03	0.46E-05	0.80E-07

TABLE VII (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 9000°K

∾ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	ρ/ρ <sub>e</sub> = 10 <sup>-5</sup>	ρ/ρ <sub>0</sub> = 10-6
23250	0.16E-03	0.44E-05	0.79E-07
23500	0.11E-02	0.34E-04	0.45E-06
23750	0.13E-02	0.42E-04	0.55E-06
24000	0.86E-03	0.27E-04	0.36E-06
24250	0.58E-03	0.18E-04	0.25E-06
24500	0.37E-03	0.11E-04	0.17E-06
24750	0.29E-03	0.85E-05	0.13E-06
25000	0.23E-03	0.67E-05	0.11E-06
25250	0.19E-03	0.55E-05	0.94E-07
25500	0.26E-03	0.78E-05	0.12E-06
25750	0.36E-02	0.12E-03	0.15E-05
26000	0.25E-02	10.80E-04	0.10E-05
26250	0.18E-02	0.57E-04	0.74E-06
26500	0.11E-02	0.35E-04	0.46E-06
26750	0.80E-03	0.25E-04	0.34E-06
27000	0.55E-03	0.17E-04	0-24E-06
27250	0.39E-03	0.12E-04	0.17E-06
27500	0/30E-03	· 0 • 87E-05	0.14E-06
27750	0/-25E-03	0.73E-05	0.12E-06
28000	0.18E-02	0.58E-04	' 0.75E-06
28250	0.37E-02	0-12E-03	0.15E-05
28500	0.23E-02	0.73E-04	0.94E-06
28750	0.17E-02 0.11E-02	0.54E-04 0.35E-04	0.70E-06 0.47E-06
<u>29000</u>	0.11E-02 0.81E-03	0.35E-04 0.25E-04	0.47E-06
· 29250 29500	0.60E-03	0.19E-04	0.26E-06
29750 29750	0.43E-03	0.13E-04	0.19E-06
30000	0.35E-03	0.10E-04	0.16E-06
30250	0.37E-03	0.11E-04	0.16E-06
30500	0.14E-02	0.43E-04	0.56E-06
30750	0.89E-03	0.28E-04	0.38E-06
31000	0.66E-03	0.20E-04	0.28E-06
31250	0.47E-03	0.14E-04	0.21E-06
31500	0.40E-03	0.12E-04	0.18E-06
31750	0.34E-03	0.98E-05	0.15E-06
32000	0.29E-03	0.81E-05	0.13E-06
32250	0.26E-03	0.72E-05	0.12E-06
32500	0.25E-03	0.68E-05	0.11E-06
32750	0.27E-03	0.78E-05	0.13E-06
33000	0.25E-03	0.71E-05	0.12E=06
33250	0.25E-03	0.71E-05	0.12E-06
33500	0.22E-03	0.60E-05	0.10E-06
33750	0.22E-03	0.60E-05	0.10E-06
34000	0.20E-03	0.55E-05	0.97E-07

TABLE VII (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 9000°K

♥ (cm <sup>-1</sup> )	$\rho/\rho_{0} = 10^{-4}$	$\rho/\rho_0 = 10^{-5}$	$\rho/\rho_0 = 10^{-6}$
34250	0.20E-03	0.55E-05	0.97E-07
34500	0.20E-03	0.55E-05	0.97E-07
34750	0.20E-03	0.54E-05	0.96E-07
35000	0.20E-03	0.54E-05	0.95E-07
35250	0.19E-03	0-53E-05	0.94E-07
35500	0.20E-03	0.53E-05	0.94E-07
35750	0.19E-03	0.52E-05	0.93E-07
36000	0.19E-03	0.52E-05	0.92E-07
36250	0.19E-03	0.52E-05	0.92E-07
36500	0.19E-03	0.51E-05	0.90E-07
36750	0.19E-03	0.51E-05	0.90E-07
37000	0-19E-03	0.51E-05	0.90E-07
37250	0.19E-03	0.51E-05	0.89E-07
37500	0.19E-03	0.50E-05	0.88E-07
37750	0.19E-03	0.50E-05	0.88E-07
38000	0.19E-03	0.50E-05	0.88E-07
38250	0.19E-03	0.50E-05	0.88E-07
38500	0.19E-03	0.50E-05	0.88E-07
38750	0.19E-03	0.50E-05	0.87E-07
39000	0.19E-03	0.49E-05	0.85E-07
39250	0.19E-03	0.49E-05	0.86E-07
39500	0.18E-03	0.48E-05	0.84E-07
39750	0.18E-03	0.48E-05	0.84E-07
40000	0.18E-03	0.48E-05	0.84E-07
40250	0.18E-03	0.47E-05	0.83E-07
40500	0.18E-03	0.47E-05	0.82E-07
40750	0.18E-03	0.46E-05	0.81E-07
41000	0.18E-03	0.45E-05	0.79E-07
41250	0.17E-03	0.44E-05	0.78E-07
41500	0.17E-03	0.44E-05	0.78E-07
41750	0.17E-03	0.44E-05	0.78E=07
42000	0.16E-03	0.43E-05	0.77E-07
42250	0.17E-03	0.43E-05	0.76E-07
42500	0.17E-03	0.44E-05	0.76E-07
·42750	0.17E-03	0.43E-05	0.76E-07
43000	0.16E-03	0.43L-05	0.75E-07
43250	0.16E-03	0.42E-05	0.74E-07
43500	0.16E-03	0.42E-05	0.73E-07
43750	0.16E-03	0.41E-05	0.73E-07
44000	0.15E-03	0.41E-05	0.72E-07
44250	0.16E-03	0.40E-05	0.68E-07
44500	0.16E-03	0.40E-05	0.68E-07
44750	0.16E-03	0.39E-05	0.67E-07
45000	0.16E-03	0.38E-05	0.66E-07
- 0000	0 1 10 1 0 3	0.005-09	0 00E 01

TABLE VII (Continued)

Radiant Emission (Watts/cm<sup>3</sup>-steradian-micron); T = 9000°K

♡ (cm <sup>-1</sup> )	$\rho/\rho_0 = 10^{-4}$	$\rho/\rho_0 = 10^{-5}$	ρ/ρ <sub>0</sub> = 10-6
, 45250	0.15E-03	0.38E-05	0.66E-07
45500	0.15E-03	0.37E-05	0.64E-07
45750	0.15E-03	0.36E-05	0.63E-07
- 46000	0.14E-03	0.36E-05	0.63E-07
46250	0.14E-03	0.36E-05	0.63E-07
46500	0.15E-03	0.36E-05	0.62E-07
46750	0.16E-03	0.37E-05	0.62E-07
47000	0.15E-03	0.36E-05	0.62E-07
47250	0.15E-03	0.35E-05	0.60E-07
47500	0.14E-03	0.35E-05	0.60E-07
47750	0.13E-03	0.33E-05	0.57E-07
48000	0.13E-03	0.32E-05	0.56E-07
48250	0.13E-03	0.31E-05	0.54E-07
48500	0.12E-03	0.31E-05	0.54E-07
48750	0.12E-03	0.31E-05	0.53E-07
49000	0.14E-03	0.32E-05	0.54E-07
49250	0.15E-03	0.32E-05	0.53E-07
49500	0.14E-03	0.31E-05	0.52E-07
49750	0.14E 03	0.31E-03	0.51E-07
50000	0.13E-03	0.30E-05	0.51E-07
50250	0.12E-03	0.30E-05	0.51E-07
50500	0.12E-03	0.29E-05	0.51E-07 0.49E-07
50750	0.11E-03	0-29E-05	0.49E-07
51000	0.12E-03	0.28E-05	0.49E-07
51250	0.12E-03	0.29E-05	0.48E-07
51500	0.12E 03	0.29E-05	0.47E-07
51750	0.13E-03	0.27E-05	
52000	0.12E-03	0.27E-05	0.46E-07
52250	0.11E-03	0.26E-05	0.46E-07
52500	0.11E-03	0.25E-05	0.45E-07 0.43E-07
52750 52750	0-10E-03		,
53000	0.10E-03	0.25E-05 0.24E-05	0.43E-07 0.42E-07
53250	1.00E-04	0.24E-05	
53500	0.10E-03	0.24E-05	0.41E-07
53750	0.10E-03 0.11E-03		0.41E-07
54000	0.11E-03	0.24E-05 0.24E-05	0.41E-07 0.40E-07
54250	0.10E-03 0.95E-04		
	0.91E-04	0.22E-05 0.22E-05	0.38E-07 0.37E-07
54500	I .		
54750	0.89E-04 0.85E-04	0:21E-05	0.36E-07
55000		0.21E-05	0.35E-07
55250	0.80E-04	0 20E-05	0.34E-07
55500.	0.79E-04	0-19E-05	0.33E-07
55750	0.79E-04	0-19E-05	0.33E-07
56000	0.73E-04	0.18E-05	0.32E-07